

PRIMARY CORNER DESCRIPTION Sec Cor for 7, 8, 17 and 18

Alias	Description
Alias	Description
Alias	Description
Alias	Description

11" Fir (1967) now stump which is out of place by approx. 30 ft. due to logging.
Using record distances from the found orig. BT and the 30" Fir stump, I reset the found brass cap. Found BTs now bears:
Orig. 24" now 37" Fir bears S.43°W., 25.1 ft. (Rec. S.45°W.)
30" Fir stump bears S.11°E., 45.2 ft. (Rec. S.12°E.)
I add marks "RESET 1982" to brass cap.
New BTS -12" Fir scribed "T32S R5W S7 CS BT" in double blaze, bears N.9°W., 83.7 ft.
11" Fir scribed "T32S R5W S8 CS BT" in double blaze, bears N.82°E., 67.9 ft.
Douglas County Surveyor Office tags on all trees.
Corner lies on very steep slope, approx. 100 ft. below new road.

BLM Dependent resurvey by Arthur R. Rambo, & Francis Simon Cadastral Surveyors under Group No. 2143, surveyed May 2006/Feb. 2007 - (DCSO records, Vol. 55 Page(s) 21690-1)

The cor. of secs. 7, 8, 17, and 18, perpetuated by the Douglas County Surveyor's Office, in 1967, and in 1982, monumented with an iron post, 1½" dia. firmly set, projecting 10" above the ground, with brass cap (properly) mkd from which the remains of an original bearing tree
A sawed fir stump, 37" dia., bears S.41½°W., 25.7 ft., with a healed blaze. (Record, S.45°W.)
and remains of a bearing tree mkd. by the Douglas County Surveyor's Office, in 1967
A sawed fir stump, 33" dia., bears S.13°E., 45.2 ft., with a healed blaze.
and the remains of BTs mkd. by the DCSO, in 1982
A fir, 19" dia., bears N.11¼°W., 83.7 ft., with a healed double blaze.
A sawed fir stump, 13" dia., bears N.78¼°E., 67.9 ft., with scribe marks 32 visible on partially healed blaze.
and new bearing trees
A madrone, 5" dia., bears N.83¼°E., 12.5 ft., mkd. X at breast height and BT at the base.
A fir, 4" dia., bears S.25°E., 15.4 ft., mkd. X at breast height and BT at the base.
A fir, 5" dia., bears S.79¼°W., 11.0 ft., mkd. X at breast height and BT at the base.
Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center, unless otherwise described in the corner description

PRIMARY CORNER DESCRIPTION Sec Cor for 7, 8, 17 and 18

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM dependent resurvey by Kevin G Mulder, Cadastral Surveyor,
under Group No. 2925; Surveyed July/Oct. 2018 - (DCSO records
Vol. 59 Page(s) 23757)

The ¼ sec. cor. of secs. 7 and 8, perpetuated by McIntosh in
2006, monumented with an aluminum post, 1½" dia., firmly set,
projecting 4" above the ground, with aluminum cap (properly)
mkd.

from which the remains of an original bearing tree

A sawed and rotted fir stump, 28" dia., bears N.35°W., 2.6
ft., with no marks visible on rotted blaze.

and bearing trees mkd. by McIntosh

A fir, 21" dia., bears N.17°E., 15.1 ft., with a healed
blaze.

A fir, 19" dia., bears N.88¾°W., 12.3 ft., with a healed
blaze.