

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 7 & 8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Oscar F. Thiel, Deputy Surveyor, under Contract #729, dated Dec. 24, 1900 and special instructions dated Sept. 12, 1901 (DCSO records Vol. 20 Page(s) 8607)

Set a cedar post, 3 ft. long, 3" sq., 24" in the ground for 1/4 sec. cor. mkd: 1/4 S7 on W face & 8 on E face, from which
 A fir, 14" dia., bears N.75°E., 10 lks., mkd: 1/4 S8 BT.
 A fir, 30" dia., bears N.35°W., 4 lks., mkd: 1/4 S7 BT.
This corner stands on W slope of ridge, 60 ft. above ft. of descent; continue ascending.

Shown as not fd on old visual

James McIntosh - For: OR Dept. of Forestry - 5/2006 - M150-56

Found - Orig. cedar post & NE BT missing
 30" Fir N.35°W., 4 lks., (now 30"x2' high rotted stump in place, partial scribed visible)
Set - Oregon State Dept. of Forestry 1 1/2"x36" alum pipe with 3 3/4" aluminum cap with magnetic insert, 34" in ground.
 18" fir N.22°E., 14.6' to aluminum nail in BT face scribed (1/4S8BT) BT tag
 WP (Orange carsonite marker CBM-250 labeled witness post) S.58°E., 3.80' to base.
 WP S.34°W., 2.80' to base.
 16" fir N.82°W., 11.9' to alum. nail in BT face scribed (1/4S7BT) BT tag
 WPCP (4"x4"x72" white painted cedar post) S.15°E., 2.3'

Lloyd R. Smith, Smith Surveying - 9/17/2014 - C.S. 65/86-22

Found - Monument not found. "MAGNET IN A WHITE PLASTIC CASE" Found in post hole.
 BTs found, good shape, tags etc. found mag nails at base of BTs.
Set - 5/8"x36" steel pin with 1 1/2" brass cap, placement of monument by swing ties from existing BTs. Placed magnet plastic case 6" down. Brass cap exposed 4" in bank of logging road.
Location - Bank of logging road.