

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 240300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 20 and 29

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Original - GLO survey by Wells Lake, Deputy Surveyor, under Contract #54, dated Feb. 19, 1855 (DCSO records Vol. 20 Page(s) 8573-74)

-----  
Set ¼ sec. post, from which  
A Skunk Wood 4" dia., bears N.10°W., 12 lks.  
A Skunk Wood 6" dia., bears S.15°E., 26 lks.

W.F. Briggs - For: H.J. Wilson (Levens Estate) - Sept. 13, 1900 - Vol. 2 Page 101

-----  
Set Post, from which  
Maple 20" dia., bears N.44°E., 23 lks. dist.  
Ash 18" dia., bears S.23°E., 22 lks.

George J. Wenderoth - June 1962 - C.S. File 52/123

-----  
1" Iron pipe ¼ corner.  
16" Cottonwood S.68°30'W., 14.1 ft.  
10" Cottonwood N.56°47'W., 43.2 ft.

BLM dependent resurvey by Joseph S. Gawron and Norman J. McDonald, under Group #472, surveyed June 1962 (DCSO records Vol. 32 Page(s) 13256)

-----  
The ¼ sec. cor., determined from the only remaining original bearing tree:

A cottonwood, 14" dia., bears S.15°E., 26 lks. dist., mkd. BT.

At the corner point

Set an iron post 30" long, 2½" dia., 26" in the ground with brass cap marked:

T 32 S R 5 W

¼ S 20

S 29

1962

from which

A Cottonwood 8" dia., bears N.52½°W., 34 lks. dist., mkd. ¼ S20 BT.

A Maple 7" dia., bears S.10½°E., 40 lks. dist., mkd. ¼ S29 BT.

An iron pipe 1" dia., firmly set, bears S.59°E., 32 lks.

See survey map filed as M 99-33. Reports corner and accessories destroyed by Cow Creek. Sept. 1985