

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 8 and 9

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - W.H. Byars, under contract # 152 survey dated June 3, 1871 (DCSO records Vol. 20 Page(s) 8587)

-----  
Set ¼ sec. post, from which  
A Laurel 6" dia., bears S.62°E., 28 lks.  
A Laurel 8" dia., bears S.45°W., 32 lks.

Survey by R.W. Brandt - For: Robert Dollar Co. - Dec. 11, 1970 - C.S. File 55/178

-----  
Considerable evidence of earlier search for the corner, however, the heartwood is very rotten on all larger Madrones, so it has been assumed the original corner is lost.  
Set 1" x 40" iron rod for the ¼ corner, from which bears:  
A 22.5" DBH I.Cedar N.53°24'E., 16.4 ft. mkd. "¼ Cor. Sec. 9, T32S R5W RS 841 BT"  
A 23.7" DBH D.Fir N.38°25'W., 72.3 ft. mkd. "¼ S Sec. 8, RS 841 BT."

James McIntosh - For: OR Dept. of Forestry - 4/2006 - M150-56

-----  
Set - Oregon State Dept. of Forestry 1½"x36" alum pipe with ¾" aluminum cap with magnetic insert, 34" in ground.  
11" fir N12°W. 28.9' to alum nail in BT face scribed (¼S8BT) BT tag.  
WP (Orange carsonite marker CBM-250 labeled witness post) N.59°E., 1.9' to base.  
10" fir S.38°E., 25.3' to alum nail in BT face scribed (¼S9BT) BT tag  
WP S.21°W., 3.0' to base  
WPCP (4"x4"x72" white painted cedar post) S.89°W., 1.9' to base.  
1" iron rod (R.A. Brandt, 1970, N.25°43'56"E., 13.12')

From Brandt's iron rod

22.5" I.Cedar (1970) N.53°24'E., 16.4' (now 31"x4' high stump 17.6' to face, scribes visible)  
23.7" fir (1970) N.38°25'W., 72.3' (now 23"x4' high rotted stump 72.7' to face, partial scribes visible)

BLM dependent resurvey by Kevin G Mulder, Cadastral Surveyor, under Group No. 2925; Surveyed July/Oct. 2018 - (DCSO records Vol. 59 Page(s) 23755)

-----  
The ¼ sec cor. of secs. 8 & 9, reestablished by proportionate measurement by McIntosh in 2006. continued next page

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 300540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 8 and 9

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

There is no remaining evidence of the original cor., therefore this position is accepted as a careful and faithful reestablishment of the cor.; monumented with an aluminum post, 1½" dia., firmly set, projecting 3" above the ground, with aluminum cap mkd.

OREGON STATE  
DEPARTMENT OF FORESTRY  
T 32 S R 5 W  
¼  
S 8 | S 9  
2006  
LS 2103

from which bearing trees mkd. by McIntosh

A fir, 14" dia., bears S.41¼°E., 25.4 ft., with a healed blaze.

A fir, 14" dia., bears N.15½°W., 28.9 ft., with a healed blaze.

From this cor., a point established by Brandt in 1970, bears N.30°44'16" E., 12.34 ft., and was not utilized during the course of this survey; monumented with an iron rod, 1" dia., firmly set, projecting 3" above the ground, from which the remains of bearing trees mkd. by Brandt

A sawed and rotted cedar stump, 31" dia., bears N.54°E., 17.6 ft., with scribe marks ¼ S9 8 T32S R5W RS841 BT visible on open blaze.

A sawed and rotted fir stump, 23" dia., bears N.38½°W., 72.8 ft., with illegible scribe marks visible on open blaze.