

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 21 and 28

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - GLO survey by Wells Lake, Deputy Surveyor, under Contract #54, dated Feb. 19, 1855 (DCSO records Vol. 20 Page(s) 8571)

Set qr. sec. post, from which
 A Y.Pine 30" dia., bears N.61°W., 23 lks.
 A Cedar 24" dia., bears S.76°E., 32 lks.

GLO survey by Oscar F. Thiel, Deputy Surveyor, under Contract #729, dated Dec. 24, 1900 and special instructions dated Sept. 12, 1901 (DCSO records Vol. 20 Page(s) 8627)

An old Cedar post bears S., 23 lks. dimly marked, witnessed as described by the Surveyor General. I reestablished by setting a Cedar post, 3 ft. long, 3" sq., 24" in the ground, marked ¼ S21 on N. face, and S28 on S. face. Corner stands in field bears N. and S.

George J. Wenderoth - 1955 - C.S. File 46/148

Wagon Axle.
 8" W.Oak S.37°12'W., 46.0 ft.
 12" B.Oak N.60°33'E., 78.4 ft.

BLM resurvey by Virgil L. Stanger, Cadastral Surveyor, under Group #1145, surveyed May/Aug. 1983 - (DCSO records Vol. 47 Page(s) 17882-83)

The ¼ sec. cor., reestablished by proportionate measurement and recorded by Wenderoth in 1956, and is accepted as the best available evidence of the position of the original corner, monumented with an iron wagon axle 2" dia., firmly set, projecting 29" above the ground, from which bearing trees mkd. by Wenderoth:

The South fork of a twin B.Oak 19" dia., bears N.61½°E., 119 lks. dist., with healed blaze.
 A W.Oak 12" dia., bears S.38¼°W., 70 lks. dist., with healed blaze.

At the corner point
 Set an iron post, 28 ins. long, 2 1/2 ins. dia., 22 ins. in the ground, with brass cap marked T 32 S R 5 W

¼ $\frac{S\ 21}{S\ 28}$
 1983

Reset wagon axle alongside iron post.
 Corner is located at intersection of fences, extending E., W., and N.