

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 9 and 16

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Original - GLO survey by Wells Lake, Deputy Surveyor, under Contract #54, dated Feb. 19, 1855 (DCSO records Vol. 20 Page(s) 8579)

Set Qr. sec. post, from which
A Fir 11" dia., bears S.55°W., 5 lks.
A Fir 12" dia., bears N.12°E., 65 lks.

Survey by Arthur Rambo L.S. #1086 - For: Medford Corp and Silver Butte Timber Co. - March 28, 1992 - M 114-78 and C.S. File 63/141

Set 5/8" x 30" rebar with 2" dia. alum. cap exposed 4" above ground mkd. "T32S R5W S9 ¼ S16 LS 1086".

Found - An indeterminate size heart of Fir tree bears S.55°W., 3.3 ft. to chaining notch. Tree mkd. ¼S BT (Orig. BT)

An indeterminate size Fir stump hole bears N.12°33'E., 43.3 ft. to center of stump hole. (Orig. BT.)

New BTs -10" Fir bears N.0°14'W., 43.9 ft. mkd. "¼ S9" in upper face, "BT" in lower face with 3/4" washer mkd. LS 1086 nailed to face.

10" Fir bears N.35°58'E., 28.2 ft. mkd. "¼ S9" in upper face and "BT" in lower face with a 3/4" washer mkd. LS 1086 nailed to face.

9" Fir bears S.31°40'E., 22.4 ft. mkd. "¼ S16" in upper face and "BT" in lower face with a 3/4" washer mkd. LS 1086 nailed to face.

13½" Fir bears S.12°52'W., 17.7 ft. mkd. "¼ S16" in upper face and "BT" in lower face with a 3/4" washer mkd. LS 1086 nailed to face.

Fd. 5/8" IR by K. DeGroot, 3/2008 - M155-23