

PRIMARY CORNER DESCRIPTION Sec Cor for 9, 10, 15 and 16

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - GLO survey by Wells Lake, Deputy Surveyor, under Contract #54, dated Feb. 19, 1855 (DCSO records Vol. 20 Page(s) 8569)

Set post, cor. to secs. 9, 10, 15 and 16 on E. slope, from which

- A W.Oak 10" dia., bears S.29°W., 20 lks.
 - A W.Oak 10" dia., bears N.69°W., 326 lks.
 - A B.Oak 18" dia., bears S.52°E., 260 lks.
- No tree near NE.

George J. Wenderoth - July 1952 - M 7-53

-
- 3/4" iron pipe.
- 50" B.Oak S.52°E., 171.6 ft.
 - 7" W.Oak S.22°W., 42.1 ft.
 - 12" W.Oak N.69°05'E., 47.0 ft.

Douglas Co. Surveyors Office - John Powell, Frank Jones, Joe Brady, crew - July 1967 - C.S. File 53/52-28

Found - 3/4" Iron pipe at section corner.

- 50" B.Oak now 50", S.52°E., 171.6 ft. Tree has been opened, "B" visible, face rotting.
- 7" now 9" W.Oak S.22°W., 42.1 ft., shows scar.
- 12" now 14" W.Oak N.69°E., 47.0 ft., shows scar.

No NW BT.

New BTs -14" W.Oak S.68°E., 40.0 ft. mkd. T32S R5W S15 CS BT
5" Cedar N.54°W., 9.7 ft. mkd. S9 CS BT.

Fence corner lies N.69°E., 28.0 ft.

Fd. OK, Max Hull, April 1990, M 110-12
Fd. OK, A. Rambo, March 1992, M 114-78
Fd. Ok, G. Lang, Sept. 1995, M 125-7
Found OK by R. Wytcherley, June 2002 - M137-46

BLM dependent resurvey by Kevin G Mulder, Cadastral Surveyor, under Group No. 2925; Surveyed July/Oct. 2018 - (DCSO records Vol. 59 Page(s) 23753)

The cor. of secs. 9, 10, 15, & 16, perpetuated from original evidence no longer in existence by Wenderoth in 1952, further perpetuated by the Douglas Co Surveyor's Office in 1967; monumented with an iron rod, 5/8" dia., firmly set in an iron pipe, 3/4" dia., projecting 2" above the ground, from which a BT mkd. by Wenderoth

- A W.Oak, 22" dia., bears N.67¼°E., 46.8 ft., with a healed blaze.

Continued next page

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 400500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 9, 10, 15 and 16

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

and a BT mkd. by the Douglas County Surveyor's Office
A W.Oak, 14" dia., bears S.68½°E., 39.8 ft., with a healed
blaze.

At the corner point

Set a stainless steel post, 28" long, 2½" dia., 25" in the
ground, directly over the iron rod and iron pipe, with brass
cap mkd.

T32S R5W
S 9 | S 10
S 16 | S 15
2018

and new bearing trees

A fir, 9" dia., bears S.12°W., 16.7 ft., mkd. T32S R5W S16
BT.

A fir, 5" dia., bears N.62¼°W., 15.5 ft., mkd. X at breast
height and BT at the base.

The geographic position in NAD 1983 (2011)

Latitude: 42°47'50.93" N. Longitude: 123°17'16.95" W.