

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 540500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 11 and 14

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wells Lake, Deputy Surveyor, under Contract #54, dated Feb. 19, 1855 (DCSO records Vol. 20 Page 8564)

Set ¼ sec. post, from which
A W.Oak 6" dia., bears S.14°W., 254 lks.
A B.Oak 10" dia., bears N.81°W., 246 lks.

W.F. Briggs, Co. Surveyor - For: G.B. Johns and Sons - July 31, 1900 - Vol. 2 Pg. 99

Set W.Oak post, as per original BT.

C.E. Roberts - Sept. 1909 - Field Book 10* Pg. 55 (& "old" corner bk, Pg. 171) *FB 10 not 9 per research 12/8/2006 JC DCSO

I set corner per original field notes. One bearing tree cut down. I took stump as BT and put in new tree:
A W.Oak marked ¼ S CS, 8" dia., bears S.3°45'E., 338 lks.

George J. Wenderoth, Deputy, Co. Surveyors Office - 1946 and 1952 - C.S. File 43/26 and C.S. File 45/98

3/4" Iron pipe.
36" W.Oak N.81°12'W., 159.7 ft.
20" Pine N.17°56'E., 158.2 ft.

Douglas Co. Surveyors Office - James W. Byron, Deputy - March 28, 1956 - C.S. File 47/75

Found - BTs as renewed by Wenderoth in 1952. The NE BT is a stump only (Pine), scribed ¼ S BT. BTs check for bearing and distance.
Also found 3/4" Iron pipe at corner under N-S fence.
I blaze and scribe:
36" Pine, S.83°E., 108.7 ft. mkd. ¼ S CS BT.

Doug. Co. Surveyors Office, Geo. Wenderoth, Deputy - Sept. 7, 1971 - C.S. File 47/75 & 56/4

Remove I.P. and set brass cap L.S. #5, at ¼ corner.
Pine BT in good shape.

Fd. OK, W. Ruppert, July 1979, M 78-29

Douglas Co. Surveyors Office - Gregory Quibell, Deputy - John Powell, crew - July 8, 1982 - C.S. File 61/36-24

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 11 and 14

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - May 6, 2014 - C.S. File 67/41-21

Found - A 3¼" dia., brass cap (properly mkd) is set flush with ground at end of drive-way in firm gravel soil. We do not disturb monument to look for any earlier mons.

A W.Oak 6" dia., is now a possible shallow root-hole fd near the rec bearing & dist of the SW orig BT.

A B.Oak 10" dia., is now a large deep and distinct root-hole, the near center of which bears N.81°W., 162.4 ft. (as per rec.) OBT

A W.Oak 8" dia., is now a semi-circle of young W.Oaks growing from the edge of a root-hole, the center of which bears S.3¾°E., 223.1 ft. (as per (1909) rec.)

A 36" Pine now a fallen out of position and very rotted approx. 28" dia., pine the root-hole of which bears S.83°E., 108.7 ft (as per (1956) rec)

A 14" W.Oak now a double trunk W.Oak the 22" dia., easterly trunk of which has a fully healed double blaze. The double trunk root crown bears S.14¼°W., 163.6 ft. (Rec. S.14½°W., 163.6 ft.) These Oaks may have grown from the edge of OBT root-hole. 1982

A 17" pine now a 32" dia., 2½ ft. tall sawn Pine stump with a fully healed double blaze; bears S.78½°E., 48.2 ft. (dist = DCSO Brg = BLM) 1982

A PPL power pole #3859; bears N.45½°W., 42.1 ft. (dist = DCSO Brg = BLM) 1982

New - A 3/4" dia., iron pipe protruding 4" above ground; bears N.1¼°E., 65.8 ft. (rec. North, 66.0 ft) This pipe was set by Wenderoth in 1946 see County Surveyor's Office file C.S. 43/26.

A 6" dia., B.Oak scribed "¼ S11 CS" "BT" on double blaze bears N.89¾°E., 92.6 ft.

Note - Monument is in open mowed yard just past end of driveway at #315 Rd.
Compass decl. 15½°E.

Fd. As per record by M. Heimbürger 9/2020 - M178-15A-C