

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 600440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 14

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - GLO survey by Wells Lake, Deputy Surveyor, under Contract #54, dated Feb.19, 1855 (DCSO records Vol. 20 Page(s) 8558)

Set qr. sec. post, from which
A Fir 16" dia., bears N.80°W., 18 lks.
A Maple 16" dia., bears N.28°E., 30 lks.

W. F. Briggs, County Surveyor - For: G.B. Johns & Sons - July 31, 1900 - Vol. 2 Page 99

Set Ash post for ¼ sec. cor. bet. secs. 13 and 14. The original BT destroyed. New BT, to wit:
Maple 30" dia., bears S.69°W., 24 lks.
No other tree near.

Frank Cain, Deputy - Recorded by F.C. Frear, County Surveyor - Oct. 14, 1920 - Field Book 107 Pg. 37 ("old" corner book, pg. 171)

Boulder 8" x 12" x 14", from which
A Maple 20" bears N.72°10'W., 116 lks.
A Maple 30" bears S.32°E., 140 lks.

Douglas Co. Surveyors Office - John Powell, Frank Jones, Joe Brady, crew - July 1967 - C.S. File 53/52-11

Found - 20" now 29" Maple N.72°W., 76.6 ft. scribing visible.
30" now 36" Maple S.32°E., 92.4 ft. tree opened, faint scribe visible, also new scribing visible
"S CS BT"
No trace of 8"x12"x14" rock, old stake at ¼ cor mkd.
"¼"

Set Brass cap at cor. mkd: County Surveyors Office
T 32 S R 5 W
¼ S14 | S13
1967

Bearing trees are in good condition.
This corner lies 4.0 ft. South of short E-W fence, approx. 100 ft. which is post of corral.

Fd. BC by Neil Hibbs, 2/2009 - M159-18
Fd. 1967 BC by D Edwards 2/2015 - M169-10