

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 1; and 6 of T32-4

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Butler Ives and George W. Hyde, under Contract #39, dated January 4, 1854 - (DCSO records Vol. 20 Page 8451)

Set ¼ sec. post, from which
A Fir 16" dia., bears N.18°E., 25 lks.
A Fir 20" dia., bears N.54°W., 52 lks.

Survey by Richard L. Templin Jr. - Sept. 1958 - C.S. 42/389

Found - 12" Fir N.54°W., 52 lks., scribing visible.
Set 3/4" Iron pipe marked: RE 3024.
Scribed -22" Fir S.15½°W., 44.0 ft. mkd. ¼S1 RE3024 BT.

Douglas Co. Surveyors Office - Larry E. Monrean, Deputy - J. Lundeen, R. Smith, crew - Nov. 7, 1984 - C.S. File 62/21-44

Found - 3/4" I.P. with metal tag stamped "RE 3024"
12" Fir now 19" dia. Fir snag, 4 ft. tall, bears N.52½°W., 34.1 ft. Scribing visible "¼ 2" (Rec. N.54°W., 34.3 ft.)
22" Fir now 24" dia. stump, tree down with scribing "RE 3024") bears S.15½°W., 44.0 ft.

We reference iron pipe and replace with 2¼" brass cap on 1" x 30" pipe and mound rocks around monument. 3/4" I.P. is buried alongside. Brass cap marked: Douglas County Surveyor

T 32 S
R5W ¼ S1 | S6 R4W
1984

New BTs -11" Incense Cedar, center of base bears N.23½°W., 57.6 ft. scribed "¼ S1 CS BT" on a double blaze.
12" Maple, center of base bears S.58°W., 35.9 ft. and scribed "¼ S1 CS BT" on a double blaze.
12" Maple, center of base bears S.34½°E., 13.2 ft. and scribed "¼ S6 CS BT" on a double blaze.
10" Fir, center of base bears S.83°E., 25.0 ft. and scribed "¼ S6 CS BT" on a double blaze.

Fd. OK - R. Templin - July 1994 - 1995-0115 A&B

BLM Dependent resurvey by Arthur R. Rambo, Cadastral Surveyor under Group No. 2707, surveyed April/May 2013 - (DCSO records, Vol. 58 Page(s) 23131-2)

The ¼ sec. cor. of secs. 1 & 6, on the E. bdy. of the Tp., perpetuated by Templin, in 1958, from evidence no longer in existence, and further perpetuated by the Douglas County Surveyors Office in 1984, monumented with an iron post, 1" dia firmly set, projecting 3" above the ground, Cont

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 700640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 1; and 6 of T32-4

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

in a collar of stone, with brass cap (properly) mkd.
from which the remains of a bearing tree mkd. by Templin Jr.
A fir stump, 24" dia., bears S.15 $\frac{3}{4}$ °W., 43.9 ft., no marks visible.
and the BTs mkd. by the Douglas County Surveyor's Office
A fir, 24" dia., bears S.85°E., 25.6 ft., with a healed blaze.
A maple, 13" dia., bears S.37 $\frac{3}{4}$ °E., 13.4 ft., with scribe marks 4 S6 CS visible on partially healed blaze.
A maple, 15" dia., bears S.57°W., 35.3 ft., with illegible scribe marks visible on partially healed blaze.
A cedar, 25" dia., bears N.22 $\frac{1}{4}$ °W., 57.5 ft., with a healed blaze.

Ron Quimby - Crew: N. Fromdahl & R. Olson - 9/2015 - C.S.
File 65/89-42

Found - 2 $\frac{1}{2}$ " DCSO brass cap (properly mkd)
24" fir S.85°E., 25.6' good scar.
13" maple S.38°E., 13.4' vis scribe
24" fir stump S.16°W., 43.9 ft. mostly rotten.
15" maple S.57°w., 35.3 ft. good scar.
27" cedar N.22°W., 57.5 ft. good scar.
Note - Lat & Long: N 42°49.124' W 123°13.690'
Cor. is on east facing slope 300'± west of road.
Compass decl. 15 $\frac{1}{2}$ °E.

Daniel Baker - For: Weyerhaeuser - 7/2019 - M176-18A-C

Found - 2 $\frac{1}{2}$ " Douglas Co. brass cap "1984"
32" fir, S.85°E., 25.9' (rec. = S.83°E., 25.0') to nail side/center - DC BT
13" Maple, S.35°E., 13.3' (rec. = S.34 $\frac{1}{2}$ °E., 13.2) to nail side/center - DC BT
15" Maple, S.58°W., 35.3' (rec. = S.58°W., 35.9') to nail side/center- DC BT
27" I.Cedar, N.25°W., 57.5' (rec.= N.23 $\frac{1}{2}$ °W., 57.6') to nail side/center - DC BT