

PRIMARY CORNER DESCRIPTION Sec. Cor. for 19 & 30; 24 & 25, T32-7

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by George W. Hyde and Charles H. Gardner, Deputy Surveyors, under Contract #54, dated Feb. 19, 1855 (DCSO records Vol. 20 Page(s) 8632)

 Set post, cor. to secs. 19, 24, 25 and 30, from which
 A Chinquapin 4" dia., bears S.72°W., 32 lks. dist.
 A Fir 12" dia., bears N.70°E., 24 lks. dist.
 A Laurel 3" dia., bears N.75°W., 75 lks. dist.
 A Laurel 5" dia., bears S.60°E., 43 lks. dist.

GLO survey by W.H. Byars, under contract # 420 survey dated Sept. 16 1861 (DCSO records Vol. 20 Page(s) 8658-59)

 Old cor. and witness trees destroyed. Set Chinquapin post, 4½ ft. long, 4" sq., 20" in ground for cor. mkd. T32S R6W S19 on NE. face; T30 on SE. face; S25 on SW. face; T32S R7W S24 on NW. face. Also two notches on S. and 4 on the N. edges of same, from which
 A Laurel 6" dia., bears N.85°E., 23 lks. dist., mkd. T32S R6W S19 BT.
 A Fir 30" dia., bears S.15°E., 28 lks. dist., mkd. T32S R6W S30 BT.
 A Laurel 8" dia., bears S.10°W., 38 lks. dist., mkd. T32S R7W S25 BT.
 A Laurel 8" dia., bears N.20°W., 44 lks. dist., mkd. T32S R7W S24 BT.

Survey by Wm. B. Paulin #552 - Wit: Robert Kischel - Jan. 6, 1962 - C.S. File 51/227

 Found - 14" Laurel N.20°W., 44 lks., had been prev. opened but found faint definite traces of scribe.
 10" Laurel N.85°E., 23 lks., had been previously opened but could find no scribing. Tree is down.
 36" Fir stump S.15°E., 28 lks. very badly rotted.
 14" Laurel S.10°W., 38 lks., had been previously opened and scribe removed. Found edge of old face. Location tag on this tree dated 1939.
 Set 1½" x 36" Iron pipe at corner.
 New BTs -8" Madrone bears N.16¼°E., 30.4 ft. scribed S19 T32S R6W BT.
 8" Chinquapin bears S.51 3/4°E., 36.5 ft. scribed S30 T32S R6W BT.
 6" Madrone bears S.11½°W., 49.0 ft. scribed S25 T32S R7W BT.
 6" Chinquapin bears N.88¼°W., 12.0 ft. scribed S24 T32S R7W BT.

PRIMARY CORNER DESCRIPTION Sec. cor. for 19 & 30; 24 & 25 of T32-7

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

BLM survey by G. Steven Popken, Cadastral Surveyor and James J. Carlson - under Group #884, surveyed Sept. 1975/June 1976 (DCSO records Vol. 37 Page(s) 15311-12)

 The Sec. cor., perpetuated and recorded by Paulin in 1962, monumented with an iron pipe 1½" dia., firmly set, projecting 10" above ground, from which the remains of the original bearing trees:

A decayed Fir stump, size indeterminate, bears S.15°E., 28 lks. dist., no marks visible.

A Madrone 18" dia., bears South, 38½ lks. dist., no marks visible on opened blaze. (Rec. S.10°W.)

and the remains of bearing trees mkd. by Paulin:

A root hole, bears N.22½°E., 45½ lks. dist., with a down Madrone alongside, 11" dia., with scribe mark W visible on open blaze.

A Chinquapin 11" dia., bears S.44¼°E., 57½ lks. dist., with scribe marks S30 T32S R6W BT visible on open double blaze.

A Madrone 9" dia., bears S.10°W., 78 lks. dist., with scribe marks S25 T32S R7W visible on open blaze.

A Chinquapin 12" dia., bears N.81½°W., 18 lks. dist., with healed double blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. dia., 22 ins. in the ground, directly atop iron pipe, with brass cap marked

```

T 32 S
R 7 W R 6 W
S 24 | S 19
S 25 | S 30
1976
    
```

from which a new bearing tree

A Chinquapin 6" dia., bears N.11 3/4°E., 13½ lks. dist., mkd. T32S R6W S19 BT.

Cor. Fd. and used in BLM survey by Roseberry, under Group #884, surveyed, June 1979 (DCSO records, Vol. 41 Pg. 16232)

Fd. OK, DCSO, Jan. 16, 1992, C.S. File 64/23-20

Fd. 1976 BLM brass cap, 3/2013 - by Wm Colisch - M165-4