

TOWNSHIP 32 RANGE 06 POINT IDENTIFIER # 109100

PRIMARY CORNER DESCRIPTION NW cor. Sec. 6, T33-6 WC

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by George W. Hyde and Charles H. Gardner, Deputy Surveyors, under Contract #54, dated Feb. 19, 1855 (DCSO records Vol. 20 Page(s) 8639)

Set post, cor. to T33S Rs. 6 & 7 W., on left bank of Cow Creek, from which
An Alder 18" dia., bears S.62°E., 22 lks. dist.
An Ash 10" dia., bears S.70°W., 35 lks. dist.
A Fir 15" dia., bears S.39°W., 67 lks. dist.

Survey by Richard R. Templin, Jr. - For: Superior Lumber Co. of Glendale - March 11, 1958 - C.S. File 42/344

Found - Orig. BT, a 12" Ash S.70°W., 35 lks. with obliterated face.
Other trees gone.
Corner falls in Cow Creek.
Set 1" Iron pipe, 35.5 ft. South of true corner as a Witness corner, marked with alum. tag stamped "RE3024", from which pipe the following trees bear:
18" Fir bears N.36°W., 23.5 ft. mkd. "S1 WC RE3024 BT"
24" Fir bears S.67¼°E., 57.5 ft. mkd. "S6 WC RE3024 BT"

BLM dependent resurvey by Joseph S. Gawron , under Group #'s350 & 526, surveyed Sept. 1963/July 1964 (DCSO records Vol. 33 Page(s) 13840-41)

(80.50 chs.)
Point for the witness corner to the standard corner of Tsp. 33 S., Rs. 6 & 7 W. At this point a witness corner has been previously established by Richard Templin in 1958, monumented with an iron pipe 1" dia., firmly set, protruding 8" above the ground, with a alum. disc, 1" dia., nailed in the center mkd. RE 3024, and an iron pipe 3/4" dia., protruding 6" above ground, firmly set alongside, from which Templin's trees:
A D.Fir 20" dia., bears N.36°W., 35 lks.dist., with a healed blaze.
A D.Fir 26" dia., bears S.67°E., 87 lks. dist., with a healed blaze.
Set an iron post, 30 ins. long, 2 1/2 ins. dia., 26 ins. in the ground, with brass cap marked

R	7	W	R	6	W
S	1		S	6	
T	33		S		
			SC		
			WC		
			1963		

from which
(Cont. Next Page)

TOWNSHIP 32 RANGE 06 POINT IDENTIFIER # 109100

PRIMARY CORNER DESCRIPTION NW Cor. Sec. 6 (Tp. corner) WC

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A D.Fir 14" dia., bears S.78°E., 90 lks. dist., mkd. XBT
A live Oak 12" dia., bears S.29°W., 128 lks. dist., mkd.
XBT.
Reset the iron pipe inside the iron post.

(81.08 chs.)
True point for the standard corner of Tps. 33 S., Rs. 6 & 7
W., determined from the only remaining original bearing tree:
An Ash 13" dia., bears S.70°W., 35 lks. dist., with a
rotted face, no marks remaining.
The corner point falls in Cow Creek, 110 lks. wide, 5
ft. deep, course S.80°W., curving N.65°W., where it is
impracticable to establish a permanent monument.

Standard corner and Wit. corner found and used in BLM survey
by Jelley and Steward, Group #703, surveyed July 1969/May
1970 (DCSO records, Vol. 35 Page 14473)

Found OK by R. Wytcherley, Feb. 2001 - M136-55
Fd. WC BC by R. Brandt 10/2018 C.S. File 65/98-11