

TOWNSHIP 32 RANGE 06 POINT IDENTIFIER # 140400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 18 and 19

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars, under contract # 420 survey dated Sept. 16 1881 (DCSO records Vol. 20 Page(s) 8693)

-----  
Set an Oak post 3 ft. long, 3" sq., 24" in the ground, for 1/4 sec. cor. mkd. 1/4 S. on N. face, from which

A Live Oak 6" dia., bears N.65°E., 20 lks. dist., mkd. 1/4 S BT.

A Fir 14" dia., bears S.62°W., 22 lks. dist., mkd. 1/4 S BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy and crew - Wit: Buzz Pounds, State Forestry - April 4, 1969 - C.S. File 54/53-37

-----  
Found - Unrecorded 5/8" I. Rod.

Orig. 14" now 28" Fir, alive, S.62°W., 14.5 ft. old bark. scribe "1/4 SBT", recent bark scribe "1/4 S19 BT", we add C.S.

Live Oak stool at approx locus of NE BT.

Set Brass cap at cor. mkd: County Surveyors Office

T 32 S R 6 W

1/4  $\frac{S \ 18}{S \ 19}$   
1969

Reset I.R. alongside brass cap.

New BT - 7" D.Fir N.58°E., 19.6 ft. mkd. 1/4 S18 CS BT.

This corner lies on very steep, rocky, southerly slope with scattered large Fir and dense Live Oak.

Fd. OK, March 1989, Greg Lang, M 108-16