

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 8 and 17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, under contract # 420 survey dated Sept. 16 1881 (DCSO records Vol. 20 Page(s) 8695)

Set an Oak post 3 ft. long, 3" sq., 24" in the ground, for 1/4 sec. cor. marked 1/4 S on N. face, from which
A Fir 20" dia., bears S.40°W., 15 lks. dist., mkd. 1/4 S BT.
A Fir 40" dia., bears N.38°W., 41 lks. dist., mkd. 1/4 S BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones, Joe Brady, crew - Sept. 1967 - C.S. File 54/31-2

Found - Orig. 20" now 33" Fir, S.40°W., 9.9 ft. bark scribe visible 1/4 S*.
**Orig. 24" Fir, now hollow rotten stump, N.50°E., 29.0 ft. (Rec. 27 ft.)
Set Brass cap at cor. mkd: County Surveyors Office
T 32 S R 6 W
1/4 S 8
S 17
1967

Reblazed and rescribed:
33" D.Fir S.40°W., 6.6 ft. (from face) scribed 1/4 S17 CS BT.
New BT - 20" D.Fir N.44°W., 42.0 ft. mkd. 1/4 S 8 CS BT.
* - 1/4 S added 4/11/2012 (DCSO JC) from orig. record
** - There are questions concerning the origin of this BT, nothing agrees with the original record. (DCSO RWS & JC 4/11/2012)

Gerald Nygren - For: Plum Creek Timber Lands - May 2012 - M163-56

Found - Douglas County brass cap & BT stumps
33" D.Fir stump, S.40°W., 6.6' (measured from orig. face) Orig.
20" D.Fir stump, N.44°W., 42.0' (slope dist from center of stump) 1967
New - 9" D.Fir bears N.82°15'W., 32.2' (BT TAG)
8" D.Fir bears N.19°E., 16.6' (BT TAG)
Measured horizontal from side-center