

PRIMARY CORNER DESCRIPTION Sec. Cor. for 28, 29, 32 and 33

Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by George W. Hyde and Charles H. Gardner, Deputy Surveyors, under Contract #54, dated Feb. 19, 1855 (DCSO records Vol. 20 Page(s) 8652-53)

-----  
 Set post cor. to secs. 28, 29, 32 and 33, from which  
 A Laurel 10" dia., bears N.8°E., 22 lks. dist.  
 A Laurel 10" dia., bears N.33°W., 63 lks. dist.  
 A B.Oak 10" dia., bears S.26°W., 47 lks. dist.  
 A Fir 5" dia., bears S.56°E., 43 lks. dist.

A.R. Evans - 1953 - C.S. File 41/241

-----  
 Found Cedar post, 2 BTs  
 18" Fir, S.50°E., 28.2 ft.  
 Madrone, N.33°W., 41.6 ft.

Douglas Co. Surveyors Office - S.J. Flause, Deputy, Terrie Plouff; Karen Mosley, crew - April 6, 1981 - C.S. 61/19-29

-----  
 Found - A cedar post approx. 12" dia. & 8 ft. long. Post has rotted off approx. 2" below ground level. The upper 5 ft. of said post has fence wires attached from fences running South and East; this section of post has rolled downhill and lies 6 ft. southeast of the above mentioned post remains in the ground.

An orig. 5" Fir now a 22" DBH D.Fir bears S.56°E., 28.4 ft. Tree has an opened face but no scribe marks are observed. Tree is opened further to reveal orig. axe marks and a scribed "T" (age verified by growth ring count)

Possible but inconclusive evidence of a stump hole is found at the record bearing and distance of the orig. NW bearing tree.

No evidence of the other orig. BTs is found.

The location of the cedar post remains in the ground, which agrees with the record bearing and distance from the orig. SE BT, is referenced out, the post remains are removed and a DCSO 1½" brass cap on a 1" x 30" iron pipe is placed in the referenced location. Cap monument firmly set and protrudes 5" from ground and mkd: DOUGLAS COUNTY SURVEYOR T32S S29 S28 S32 S33 R6W 1981.

New BTs -10" DBH D.Fir bears N.51½°E., 26.0 ft. Tree is scribed T32S R6W S28 CS BT on a double blaze.

6" DBH W.Fir bears S.32°W., 29.6 ft. Tree is scribed T32S R6W S32 CS BT on a double blaze.

11" DBH D.Fir bears N.03°W., 28.6 ft. Tree is scribed T32S R6W S29 CS BT on a double blaze.

All BTs are tagged with DCSO BT tags.

Cont.

PRIMARY CORNER DESCRIPTION Sec. Cor. for 28, 29, 32 and 33

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Fd. a 1¼" IP by DCSO in 1981, firmly set & projecting 5" above ground, with properly mkd. 2½" brass cap per rec. with accessories as per rec. by A. DeGroot, 10/2016 - M171-19 NAD 83 (CORS 96)  
Lat: 42°45'15.09580"N Long: 123°25'35.46444"W

Douglas Co. Surveyors Office - Crew: Stephen J Flause & Mike Koch - 4/4/2016 (filed 3/17/2020) - C.S. File 67/46-18

Found - A 1" i.d. iron pipe by Flause, in 1981, firmly set, projecting 3" above the ground with a 2½" dia. brass cap (properly) marked

An original BT Hyde and Gardner, in 1855 -  
A root hole bears S.56°E., 28.4 ft. with a rotted 21"x2 ft. tall fir stump is tipped downhill out of position.

BTs by S. J. Flause in 1981 -  
A root hole bears N.51½°E., 26.0 ft. with a D.Fir stump tipped out of position, upside down and buried laying alongside.

A 15" Grand Fir bears S.32°W., 29.0 ft. with a healed blaze. (Rec. 29.6 ft.)

A 22" D.Fir bears N.3°W., 28.6 ft. with a healed blaze.

New BTs- A 11" Grand Fir bears N.30°E., 42.2 ft. scribed "T32S R6W S28" "CS BT"

A 9" Maple bears S.82½°E., 34.8 ft. scribed "T32S R6W S33" "CS BT"

Note - All bearing trees have BT tags attached. All new bearing trees have double blazed faces with bearings measured to the center of the tree at the root crown and distances measured to the side and center of the root crown.

Monument falls near the bottom of a shallow draw in the NW corner of new clearcut with older reprod. fir in the NE and partial cut old growth in the SW.

Compass decl. 15°E.