

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 20 and 21

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, under contract # 420 survey dated Sept. 16 1881 (DCSO records Vol. 20 Page(s) 8683)

Set a Laurel post 3 ft. long, 3" sq., 24" in the ground, for 1/4 sec. cor., marked 1/4 South on W. face, from which
A Laurel 6" dia., bears N.47°E., 30 lks. dist., mkd. 1/4 S BT.
An Oak 6" dia., bears N.15°W., 22 lks. dist., mkd. 1/4 SBT.

BLM Resurvey by Lynn M. Roseberry, Cadastral Surveyor - Under Group #910 Surveyed, Aug/Sept. 1976 - (DCSO records Vol. 41 Page(s) 16319)

Point for the 1/4 sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 28 ins. long, 2 1/2 ins. dia., 24 ins. in the ground, with brass cap marked
T 32 S R 6 W
1/4
S 20 | S 21
1976
from which
A Fir 15" dia., bears S.83°E., 67 lks., mkd. 1/4 S21 BT.
A Fir 26" dia., bears N.10 1/2°W., 49 lks., mkd. 1/4 S20 BT.

BLM dependent resurvey by Francis J. Simon, Cadastral Surveyor under Group #2125, surveyed July/Nov. 2005 - (DCSO records Vol. 55 Page(s) 21473)

The 1/4 sec. cor. of secs. 20 and 21, monumented with an iron post, 2 1/2", firmly set, projecting 7" above the ground, with brass cap mkd.
T 32 S R 6 W
1/4
S 20 | S 21
1976
from which bearing trees mkd. by Roseberry and Aanrud
A fir, 18" dia., bears S.83°E., 44.2 ft., with a healed blaze.
A fir, 32" dia., bears N. 10 1/2° W., 31.3 ft., with a healed blaze. (Record, 32.3 ft.)