

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 16 and 17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, under contract # 420 survey dated Sept. 16 1881 (DCSO records Vol. 20 Page(s) 8684)

Set a Fir post, 3 ft. long, 3" sq., 24" in the ground, for 1/4 sec. cor. mkd. 1/4 S. on W. face, from which

A Fir 18" dia., bears S.80°E., 12 lks. dist., mkd. 1/4 S BT

A Fir 14" dia., bears N.70°W., 20 lks. dist., mkd. 1/4 S BT

BLM Resurvey by Lynn M. Roseberry, Cadastral Surveyor - Under Group #910 Surveyed, Aug/Sept. 1976 - (DCSO records Vol. 41 Page(s) 16322)

Point for the 1/4 sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2 1/2 ins. dia., 24 ins. in the ground, with brass cap marked T 32 S R 6 W

1/4
S 17 | S 16
1979

from which

A Fir 10" dia., bears N.45°E., 47 lks. dist., mkd. 1/4 S16 BT.

A Fir 11" dia., bears N.16°W., 60 lks. dist., mkd. 1/4 S17 BT.

Tony Hostetter - For: Weyerhaeuser Co. - April 12, 2016 - C.S. File 65/102-22

Found - 2 1/2" iron pipe w/brass cap, 0.5 ft out of ground as set by Roseberry for BLM in 1976

10" decayed fir stump, no marks, 1976 BT, bears; N.45°E., 31.0 ft to center.

New BTs- 7" Fir, BT tag, bears: N.46°E., 18.7 ft to 6" spike, placed below tag.

7" Fir, BT tag, bears: N.80°W., 26.0 ft to 6" spike, placed below tag.

11" Fir, BT tag, bears: S.77°W., 13.4 ft to 6" spike placed below tag.

11" Fir, BT tag, bears; N.41°W., 21.5 ft to 6" spike placed below tag.