

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 14 and 15

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by W.H. Byars, under contract # 420 survey dated Sept. 16 1881 (DCSO records Vol. 20 Page(s) 8672)

Set a Fir psot, 3 ft. long, 3" sq., 24" in the ground, for 1/4 sec. cor., marked 1/4 S. on W. face, from which
A Fir 15" dia., bears N.32°E., 12 lks. dist., mkd. 1/4 S BT
A Fir 18" dia., bears N.5°W., 15 lks. dist., mkd. 1/4 S BT

BLM resurvey by Rollin D. Aanrud, Cadastral Surveyor, under Group #616, surveyed June 1966/March 1967 (DCSO records Vol. 34 Page(s) 13984)

Point for the 1/4 sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 28 ins. long, 2 1/2 ins. dia., 24 ins. in the ground, with brass cap marked
T 32 S R 6 W
1/4
S 15 S 14
1966

from which
A Fir 14" dia., bears S.55°E., 70 lks. dist., mkd. 1/4 S14 BT.
A Cedar 16" dia., bears N.74°W., 26 lks. dist., mkd. 1/4 S15 BT.
Corner falls on S. bank of a creek, 2 lks. wide, course E.

BLM survey by Mark Dixon and Henry Hartley, Cadastral Surveyors, under Group #1337, surveyed July/Sept. 1989 (DCSO records Vol. 48 Page(s) 18568-69)

The 1/4 sec. cor., monumented with an iron post, 2 1/2" dia., firmly set, projecting 6" above ground, with 1966 brass cap from which bearing trees mkd. by Aanrud
A Fir 18" dia., bears S.55°E., 70 lks. dist., with healed blaze.
A Cedar 22" dia., bears N.74°W., 26 lks. dist., with healed blaze.
and a bearing tree mkd. by person(s) unknown
A Fir 26" dia., bears N.70 3/4°W., 109 lks. dist., with axe marks visible on an opened blaze.