

TOWNSHIP 32 RANGE 06 POINT IDENTIFIER # 500600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2, 3, 10 and 11

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 survey by W.H. Byars, under contract # 420 survey dated Sept. 16 1881 (DCSO records Vol. 20 Page(s) 8674-75)

-----  
Set a Fir post, 4 ft. long, 4" sq., 24" in the ground, for the cor. to secs. 2, 3, 10 and 11, marked T32S R6W S2 on NE.; S11 on SE.; S10 on SW.; and S3 on NW. faces, with 5 notches on S. and 2 notches on E. edges, from which

- A Fir 14" dia., bears N.35°E., 19 lks. dist., mkd. T32S R6W S2 BT.
- A Fir 16" dia., bears S.65°E., 28 lks. dist., mkd. T32S R6W S11 BT.
- A Fir 20" dia., bears S.60°W., 9 lks. dist., mkd. T32S R6W S10 BT.
- A Fir 18" dia., bears N.26°W., 30 lks. dist., mkd. T32S R6W S3 BT.

Douglas County Surveyors Office - James Byron, Deputy - Milo Godfrey, S.A. Bilow, crew - June 9, 1959 - C.S. File 49/91-4

- Found - Orig. 24" now 20" rotted stump, N.35°E., 12.5 ft., shows old scar.  
Orig. 18" now 24" Fir snag, shows good scribing "S 3 R"  
Orig. 20" now 40" Fir S.60°W., 5.9 ft. shows good scars, I do not open.  
Orig. 16" now 40" Fir S.65°E., 18.5 ft., shows good scars, I do not open.

Set Brass cap at cor. mkd: County Surveyors Office

T 32 S R 6 W  
S 3 | S 2  
S 10 | S 11  
1959

- New BTs -18" R.Fir bears N.58°W., 24.6 ft. scribed S3 T32S R6W CS BT.  
18" R.Fir bears N.37°E., 88.6 ft. scribed S2 T32S R6W CS BT.  
22" R.Fir bears S.28°E., 60.6 ft. scribed S11 T32S R6W CS BT.  
25" R.Fir bears West 33.8 ft. scribed S10 T32S R6W CS BT.

Cor. Fd. and used in BLM survey by R. Aanrud, under Group #1018, surveyed June/Aug. 1980 (DCSO records, Vol. 44 Page 16984-85)

(Cont. Next Page)

TOWNSHIP 32 RANGE 06 POINT IDENTIFIER # 500600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2, 3, 10 and 11

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Survey by Orrin K. Frederick, L.S. #1987 - For: Boise Cascade  
Timberlands of OR - Feb. 21, 1985 - C.S. 63/11 and M 90-67

-----  
Found - 1959 DCSO brass cap monument, firmly set, exposed  
14".  
45" Fir bears S.65°E., 18.5 ft. healed blaze.  
40" Fir stump bears S.60°W., 6.0 ft. with healed  
blaze.  
20" Fir snag bears N.37°E., 88.5 ft. with healed  
blaze.  
26" Fir bears S.28°E., 60.7ft. with scribing  
visible.

There being no other suitable trees available within limits:  
I Set 5/8" x 30" iron rebars with LS 1987 plastic cap as  
follows:

For Sec. 2: N.19°08'E., 28.68 ft., on road cut bank.

For Sec. 3: N.67°23'W., 34.32 ft., edge of road.

For Sec. 10: S.84°04'W., 26.41 ft., edge of road.

Corner lies approx. 10 ft. southerly of Rd. #32-6-3.

BLM survey by Dixon and Hartley, 1989, (DCSO records, Vol. 48  
Pages 18571-72) - Fd. 1959 DCSO brass cap,; 3 orig. BTs; 2  
Byron BTs; 3 reference monuments by Frederick AND a bearing  
tree by person(s) unknown:

A Fir 38" dia., bears S.31¼°E., 51 lks. dist. with scribe  
mark B visible on the bark.

BLM dependent resurvey by Francis J. Simon, Cadastral  
Surveyor under Group #2125, surveyed July/Nov. 2005 - (DCSO  
records Vol. 55 Page(s) 21468-9 & 21467)

-----  
The cor. of secs. 2, 3, 10, and 11, monumented with an iron  
post, 1½" dia., firmly set, projecting 12" above the ground,  
with brass cap mkd. COUNTY SURVEYORS

|              |  |      |
|--------------|--|------|
| S 3          |  | S 2  |
| S 10         |  | S 11 |
| T 32 S R 6 W |  |      |
| 1959         |  |      |

from which the remains of the original bearing trees

A fir, 55" dia. bears S.65°E. 18.5 ft. with a healed blaze

A sawed fir stump, 38" dia., bears S.60°W., 5.9 ft., with  
a healed blaze.

and the remains of BTs mkd. by the Doug Co Surveyor's Office

A fir snag, 19" dia., bears N.36°E., 87.8 ft., with a  
healed double blaze.

A fir snag, 21" dia., bears S.29°E., 60.7 ft., with scribe  
marks T32S R6W S11 CS visible on partially healed blaze

continued next page

TOWNSHIP 32 RANGE 06 POINT IDENTIFIER # 500600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2, 3, 10 and 11

|             |                   |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

and a bearing tree mkd. by person(s) unknown and called for by Dixon and Hartley

A fir, 38" dia., bears S.31¼°E., 33.7 ft., with cruiser mark SR visible in the bark.

and the remains of RMs set by Frederick, in 1985

An iron rod, 5/8" dia., firmly set, projecting 4" above the ground, bears N.19°19'E., 28.7 ft., with yellow plastic cap mkd. FREDERICK LS1987.

An iron rod, 5/8" dia., firmly set, 2" below the ground, with the top 6" bent toward the S., bears S.84°06'W., 26.4 ft.

and new bearing trees

A fir, 6" dia., bears S.66½° W., 34.6 ft., mkd. T32S R6W S10 BT.

A fir, 9" dia., bears N.54¼°W., 34.5 ft., mkd. T32S R6W S3 BT.

Corner is located 13 ft. E. of a graveled road, 15 ft. wide, bears N.25°E. and S.25°W.

The geographic position (NAD 1983 (CORS 96)) of the corner of sections 2, 3, 10, and 11, as determined by a conventional tie to a temporary point, established utilizing NAVSTAR GPS static data and National Geodetic Survey OPUS with continuously operating reference stations "FICKLEHILL", "BALDMTN", and "YREKA", is as follows:

Latitude: 42° 48' 43.02" N.

Longitude: 123° 23' 13.87" W.