

TOWNSHIP 32 RANGE 06 POINT IDENTIFIER # 640600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 1 and 12

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, under contract # 420 survey dated Sept. 16 1881 (DCSO records Vol. 20 Page(s) 8668)

Set a Fir post, 3 ft. long, 3" sq., 22" in the ground, for 1/4 sec. cor., marked 1/4 S. on N. face, from which
A Fir 42" dia., bears S.89°E., 53 lks. dist., mkd. 1/4 S BT.
An Alder 5" dia., bears N.42°W., 21 lks. dist., mkd. 1/4 S BT.

BLM resurvey by Rollin D. Aanrud, Cadastral Surveyor, under Group #1018, surveyed June/Aug. 1980 (DCSO records Vol. 44 Page(s) 16981)

Point for the 1/4 sec.cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2 1/2 ins. dia., 24 ins. in the ground, with brass cap marked

T 32 S R 6 W
1/4 $\frac{S 1}{S 12}$
1980

from which

A Cedar 9" dia., bears S.33 3/4°W., 22 lks. dist., mkd. 1/4 S12 BT.

A Fir 19" dia., bears N.1°W., 71 lks. dist., mkd. 1/4 S1 BT.

Found OK by K. Hoffine, Nov. 2002 - M141-34