

TOWNSHIP 32 RANGE 07 POINT IDENTIFIER # 140600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 6 and 7

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 420 survey dated Sept 16 1881 (DCSO records Vol. 21 Page(s) 8764)

Set a Cedar post, 4 ft. long, 4" sq., 20" in the ground, marked $\frac{1}{4}$ S on N. side, for the $\frac{1}{4}$ sec. cor., from which
A Pine 40" dia., bears S.73°W., 17 lks. mkd. $\frac{1}{4}$ S BT.
A Pine 48" dia., bears N.35°W., 57 lks. mkd. $\frac{1}{4}$ S BT.

Two large pines not found. Area badly burnt. 4/1968 by JP DCSO - C.S. File 54/36-115

BLM resurvey by Lynn M. Roseberry and Rollin D. Aanrud, Cadastral Surveyors, Under Group #'s 350 and 960, surveyed Aug/Sept. 1978 (DCSO records Vol. 42 Page(s) 16507)

Point for the $\frac{1}{4}$ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2 1/2 ins. dia., 24 ins. in the ground, with brass cap marked T 32 S R 7 W

$\frac{1}{4}$ $\frac{S\ 6}{S\ 7}$
1978

from which

A Fir 8" dia., bears N.60°E., 32 lks. mkd. $\frac{1}{4}$ S6 BT.

A Fir 8" dia., bears S.59 $\frac{1}{2}$ °W., 23 lks. mkd. $\frac{1}{4}$ S7 BT.

Corner is located at top of ascent, slopes S.