

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 19 and 20

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 420 survey dated Sept 16 1881 (DCSO records Vol. 21 Page(s) 8757)

Marked a Pine, 60" dia., with large blaze and ¼ S on W., also two notches on N. and S. sides for the ¼ sec. cor., from which

- A Pine 60" dia., bears N.30°E., 75 lks. mkd. ¼ S BT.
- A Pine 48" dia., bears S.30°W., 8 lks. mkd. ¼ S BT, open timbers.

Survey by Milner L. Larsen, RE #3642 - August 11, 1954 - C.S. File 41/289

I find a 40" Yellow Pine windfall, broken off just above the ground, marked ¼ S on West face, from which

- A Y.Pine 48" dia., bears N.30°E., 75 lks., no scribing remains on the tree.
- A Y.Pine 32" dia., bears S.30°W., 8 lks., this tree is also a windfall, no scribing remaining.

On the West side of the stump of the tree marked for the ¼ corner, I drive a 1" steel bolt, 24" long, 18" in the ground, from which

- A Laurel 8" dia., bears N.24½°W., 19.3 ft. mkd. 2968 BT.
- A Laurel 6" dia., bears S.55°E., 15.3 ft. mkd. 2968 BT.

Fd. OK, DCSO, J.Powell, Dec. 4, 1967, C.S. File 54/36-105

Douglas County Surveyors Office - Karen Reed, Frank C. Silagy; Gary Langlitz (2nd Visit) - Aug. 21, 1978 and Sept. 5, 1978 - C.S. File 60/17-1

Found - An orig. Pine corner tree (Rec. 60") now burnt, rotted and broken off at ground level. No scribing visible.

- A 1" x 24" Iron bolt on West side of tree.
- An orig. 60" Pine, now a 43" stump, bears N.34°E., 52.3 ft. from center of cor. tree to center of brg. tree. (Rec. N.30°E., 49.5 ft.), rotted blaze, no scribing.
- A root hole bears S.30°W., 6.0 ft. with orig. Pine alongside. No scribing visible. Brg. & Dist. from center of cor. tree to center of root hole.
- An 8" Laurel (Madrone) now 11" bears N.22°W., 19.3 ft. (Rec. N.24°W.) with visible scribing on partially healed blaze. Scribing not readable.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 19 and 20

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A 6" Laurel (Madrone) now rotted with only face standing, bears S.55°E., 15.3 ft. visible scribing "2968 BT". Laurel measures from center of tree to I.Bolt.

Replace Iron bolt with 1" x 36" I.Pipe with brass cap at brg. and dist. from BTs by Larsen. Set bolt on East side of cap, West side of tree. Cap bears N.55°W., 2.5 ft. from center of cor. tree, stamped cap: Douglas Co. Surveyor
T 32 S R 7 W
1/4 S19|S20
1978

Returned to cor.to find BLM had added "WC 2.5 ft. c_or" to cap

New BTs -An 11" D.Fir bears S.40°E., 40.8 ft. scribed ¼ S20 CS BT on double blaze. Returned to add "WC" at top of blaze.

A 10" D.Fir bears S.71°W., 16.8 ft. scribed "WC ¼ S19 CS BT" in a double blaze. This tree scribed on 2nd visit.

BLM Dependent resurvey by Stephan L. Barott, Cadastral Surveyor (Forest Service, USDA) under Group #1995, surveyed April/Nov. 2002 - (DCSO records Vol. 54 Page(s) 21168-9)

The ¼ sec. cor. of secs. 19 & 20, monumented with the remains of the original pine corner tree, rotted and broken off at ground level, perpetuated by Douglas. J. Theno, Registered Engineer No. 2968, recorded in C. S. file No. 41/289 in 1954, and further perpetuated by the Douglas County Surveyor's Office in 1978, from which the remains of the original BTs:

A sawed pine stump, 43" dia, bears N.33¼°E., 53.5 ft., with no scribe marks visible. (Rec. N.30°E., 49.5 ft.)

A root hole, bears S.30°W., 5.3 ft.

and the remains of bearing trees mkd. by Theno

A madrone clump with decayed center, size indeterminate, bears S.51½°E., 14.4 ft., with no scribe marks visible

A madrone, 13" dia, bears N.28°W., 20.5 ft., with a healed blaze.

and bearing trees mkd. by the County Surveyor's Office

A fir, 20" dia, bears S.41¾°E., 38.5 ft., with a healed blaze.

A fir, 17" dia, bears S.76°W., 18.7 ft., with a healed blaze.

At the corner point

Remove the rotted remains of the corner tree and set a stainless steel post, 28" long, 2½" dia., 24" in the ground, in a collar of stone, with brass cap mkd.

continued next page

TOWNSHIP 32 RANGE 07 POINT IDENTIFIER # 200340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 19 and 20

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

T 32 S R 7 W
1/4
S 19 | S 20
2002

Deposit a magnet in a white plastic case at the base of the stainless steel post.

From this point, a point established by Theno, perpetuated by the Douglas County Surveyor's Office in 1978, monumented with an iron pipe, 1" dia., firmly set, flush with the ground, with brass cap mkd. DOUGLAS COUNTY SURVEYOR WC ¼ S19 S20 T32S R7W 1978 2.5 FT. TO COR, and an arrow pointing to the cor., bears N.57°28'00"W., 2.5 ft.

Fd. & used on BLM Dependent resurvey by Arthur R. Rambo, Cadastral Surveyor under Group No. 2179, surveyed July/Nov. 2007 - (DCSO records, Vol. 55 Page(s) 21607-8)