

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 20 and 29

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 420 survey dated Sept 16 1881 (DCSO records Vol. 21 Page(s) 8755)

Set a Laurel post, 4 ft. long, 4" sq., 24" in the ground, mkd. ¼ on N. side for the ¼ sec. cor., from which:
A Laurel 6" dia., bears S.88°W., 11 lks. mkd. ¼ S BT.
A Laurel 8" dia., bears N.35°W., 39 lks. mkd. ¼ S BT.

BLM resurvey by Lynn M. Roseberry and Rollin D. Aanrud, Cadastral Surveyors, Under Group #'s 350 and 960, surveyed Aug/Sept. 1978 (DCSO records Vol. 42 Page(s) 16498)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28" long, 2½ dia., 24" in the ground, with brass cap marked

T 32 S R 7 W
1/4 S 20
 S 29
1978

from which

A Fir 12" dia., bears N.36½°E., 43 lks. mkd. ¼ S20 BT.
A P.Pine 19" dia., bears S.9°E., 61½ lks. mkd. ¼ S29 BT

BLM Dependent resurvey by Stephan L. Barott, Cadastral Surveyor (Forest Service, USDA) under Group #1995, surveyed April/Nov. 2002 - (DCSO records Vol. 54 Page(s) 21164-5)

The ¼ sec. cor. of secs. 20 & 29, monumented with an iron post, 2½ " diam., firmly set, 24" below ground in fill slope of BLM gravel road no. 32-7-20, with brass cap mkd.

T 32 S R 7 W
¼ S 20
 S 29
1978

from which bearing trees mkd. by Roseberry and Aanrud

A fir, 21" dia., bears N.36½°E., 28.4 ft., with a healed blaze.

A pine, 29" dia., bears S.9°E., 40.6 ft., with a healed blaze.