

PRIMARY CORNER DESCRIPTION Sec. Cor. for 4, 5, 8 and 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 420 survey dated Sept 16 1881 (DCSO records Vol. 21 Page(s) 8749-50)

-----  
Set a Cedar post, 4 ft. long, 4" sq., 20" in ground for the cor. to secs. 4, 5, 8 and 9 marked T32S R7W S4 on NE.; S9 on SE.; S8 on SW.; S5 on NW.; also 5 notches on the S. and 4 notches on E. sides, from which

- A Pine 30" dia., bears N.64°E., 68 lks. mkd. T32S R7W S4 BT.
- A Pine 36" dia., bears S.10°E., 102 lks. mkd. T32S R7W S9 BT.
- A Pine 36" dia., bears S.22°W., 81 lks. mkd. T32S R7W S8 BT.
- A Fir 36" dia., bears N.30°W., 36 lks. mkd. T32S R7W S5 BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones, crew - November 28, 1967 - C.S. File 54/36-98

-----  
 Found - Orig. 30" now 35" S.Pine N.60°E., (Rec. N.64°E.) 44.9 ft., faint scribe marks visible.  
 Orig. 36" now 37" S.Pine S.5°E., (Rec. S.10°E.) 67.3 ft., faint scribe visible, 2 S 9  
 Orig. 36" now 36" D.Fir N.30°W., 23.8 ft., faint scribe visible, T32S R7W S5 B  
 Orig. 36" S.Pine, now stump, S.28°W., 50.6 ft. (Rec. S.22°W., 53.5 ft.)

By using 1 bearing and 3 distances, I renew section corner. Set Brass cap at cor. mkd: County Surveyors Office

T 32 S R 7 W  
 S 5 | S 4  
 S 8 | S 9  
 1967

New BTs- 9" D.Fir S.56°E., 34.5 ft. mkd. T32S R7W S9 CS BT.  
 26" Y.Pine N.74°E., 38.4 ft. mkd. T32S R7W S4 CS BT  
 18" D.Fir N.49½°W., 29.4 ft. mkd. T32S R7W S5 CS BT  
 7" Madrona S.72½°W., 53.0 ft. mkd. T32S R7W S8 CSBT

Cor. Fd. and used in BLM resurvey by Jelley, Group #1086, surveyed April/June 1982 (DCSO records, Vol. 46 Pages 17563-64)