

TOWNSHIP 32 RANGE 07 POINT IDENTIFIER # 340400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 16 and 21

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by W.H. Byars, Deputy Surveyor under contract # 420 survey dated Sept 16 1881 (DCSO records Vol. 21 Page(s) 8747)

-----  
Set a Fir post, 4 ft. long, 4" sq., 24" in the ground, mkd. 1/4 S on N. side for the 1/4 sec. cor., from which  
A Fir 10" dia., bears S.45°E., 25 lks. mkd. 1/4 S BT.  
A Fir 36" dia., bears N.65°W., 34 lks. mkd. 1/4 S BT.

Survey by Norman D. Price, For: Dollar and Patterson Lumber Co. - May 1956 - C.S. File 42/143-2

-----  
Determined at the record bearing and distance from each of the original bearing trees, both of which will be destroyed during construction of logging roads.  
Set an iron post, 3 ft. long, 1 1/2 ins. dia., 28 ins. in the ground mkd. RS33.  
From which new bearing trees:  
A D.Fir 10" dia., bears S.73°E., 98 lks. dist., mkd. 1/4 S21 RS33 BT.  
A D.Fir 10" dia., bears N.77°W., 184 lks. dist., mkd. 1/4 S16 RS33 BT.

Fd. OK, DCSO, J.Powell, Nov. 1967, C.S. File 54/36-136

BLM remonumentation by Lynn M. Roseberry and Rollin D. Aanrud, Cadastral Surveyors, Under Group #'s 350 and 960, surveyed Aug/Sept. 1978 (DCSO records Vol. 42 Page(s) 16511-12)

-----  
The 1/4 sec. cor., determined at record bearing and distance from the remains of an original bearing tree:  
A sawed and shattered Fir stump, 36" dia., bears N.65°W., 34 lks. dist., illegible scribe marks visible on detached bark blaze.

and a bearing tree mkd. by Price in 1956:

A Fir 12" dia., bears N.77°W., 184 lks. dist., with scribe marks S16 visible on partially opened blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. dia., 24 ins. in the ground, with brass cap marked

T 32 S R 7 W  
1/4 S 16  
S 21  
1978

from which new bearing trees

A Fir 7" dia., bears N.48 1/4°W., 38 lks. dist., mkd. 1/4 S16 BT.

(Cont. Next Page)

TOWNSHIP 32 RANGE 07 POINT IDENTIFIER # 340400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 16 and 21

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A Fir 6" dia., bears S.48 3/4°E., 61 lks. dist., mkd. ¼ S21 BT.  
Corner is located in cut bank at W. edge of an abandoned dirt road, 25 lks. wide, bears NE. and SW.

Ron Quimby - Crew: N. Fromdahl & R. Olsen - 7/2015 - C.S.  
File 65/89-12

-----  
Found - BLM Brass cap  
12" Fir, S.48°E., 40.3 ft. good scar.  
18" Fir, N.77°W., 121.4 ft. good scar.  
20" Fir N.48°W., 25.1 ft. good scar.  
Set - 4" Fir N.22°E., 3.6 ft. scribed ¼ S16 BT.  
Note - Hand held Lat & Long: N.42°46'.949' W.123°32.081'  
Cor. in cut bank west side of road.  
Compass decl. 15½°E.