

TOWNSHIP 32 RANGE 07 POINT IDENTIFIER # 440700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 3; and 34 of T31-7

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 420 survey dated Sept 16, 1881 (DCSO records Vol. 19 Page(s) 8025)

Set a Pine post, 4 ft. long, 4" sq., 18" in ground marked ¼ S on the side for the ¼ sec. cor., from which
A Laurel 28" dia., bears N.45°E., 47 lks. mkd. ¼ S BT.
A Cedar 26" dia., bears S.48°W., 47 lks. mkd. ¼ S BT.

BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #531, surveyed Oct. 1963\June 1964 (DCSO records Vol. 33 Page(s) 13619)

The ¼ sec. cor., determined at record bearing and distance from the remains of the original bearing trees:

A Madrone stump hole bears N.45°E., 47 lks. dist.
A Cedar 53" dia., bears S.48°W., 47 lks. dist., with old axe marks on the bark, facing the corner point. This tree has been sawed into recently, but no blaze was found.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. dia., 24 ins. in the ground, with brass cap marked

T 31 S R 7 W
¼ S 34
S 3
T 32 S R 7 W
1964

from which new bearing trees

A Fir 8" dia., bears N.43°E., 26 lks. dist., mkd. ¼ S34 BT
A Fir 8" dia., bears S.23°W., 73 lks. dist., mkd. ¼ S3 BT.