

TOWNSHIP 32 RANGE 07 POINT IDENTIFIER # 500140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 34 and 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 420 survey dated Sept 16 1881 (DCSO records Vol. 20 Page(s) 8724)

Set a Laurel post 4 ft. long, 4" sq., 18" in the ground, for the ¼ sec. cor., from which
A Fir 56" dia., bears N.30°E., 64 lks. dist., mkd. ¼ S BT.
A Laurel 18" dia., bears N.10°W., 34 lks. dist., mkd. ¼ S BT.

Not found. All large Fir trees in area opened. Also laurels opened 56" fir probably bark scribed therefore scribing being destroyed. Continued work on large fir which fit call from ridge with no results, by J.P. DCSO 3/13/1968 C.S. File 54/36-113 (added 10/12/2016)

Survey by Ronald Quimby, L.S. #1654 - For: Boise Cascade Timberlands of Or. - May 1983 - M 94-27

Set 2½" x 30" alum. pipe, flush with ground with 3" cap mkd: T32S R7W WM 1/4 S34 S35 1983 RLS 1654.
New BTs -6" D.Fir bears N.89°E., 19.5 ft., faced and scribed ¼ S35 BT.
8" Tan Oak bears N.12°W., 37.0 ft. faced and scribed ¼ S34 BT.

Cor. Fd. and accepted in BLM resurvey by Nickerson and Caster, under Group #1528, surveyed March/April 1990 (DCSO records, Vol. 50 Page 18989)

BLM Dependent resurvey by Stephan L. Barott, Cadastral Surveyor (Forest Service, USDA) under Group #1995, surveyed April/Nov. 2002 - (DCSO records Vol. 54 Page(s) 21174)

The ¼ sec. cor. of secs. 34 & 35, monumented with an aluminum post, 2½" dia., firmly set, 6 ins. below ground level, on the edge of an old cat road, with an aluminum cap (properly) mkd, from which a bearing tree mkd. by Quimby, reported by Nickerson and Caster
A fir, 14" dia. bears N.89°E. 19.5 ft. with a healed blaze and a new bearing tree
A fir, 7" dia., bears N.10½°W., 67.4 ft., mkd. ¼ S34 BT.
Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center, unless otherwise described in the corner description