

PRIMARY CORNER DESCRIPTION Sec. cor. for 2, 3, 10 and 11

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 420 survey dated Sept 16 1881 (DCSO records Vol. 20 Page(s) 8730-31)

Marked a Fir, 6" dia., for the corner to secs. 2, 3, 10 and 11 marked T32S R7W S2 on NE.; S11 on SE.; S10 on SW.; and S3 on NW., with five notches on the S. and two notches on E. angles, from which

- A Fir 36" dia., bears N.62°E., 97 lks. dist., mkd. T32S R7W S2 BT.
- A Fir 48" dia., bears S.22°E., 46 lks. dist., mkd. T32S R7W S11 BT.
- A Fir 40" dia., bears S.38°W., 89 lks. dist., mkd. T32S R7W S10 BT.
- A Fir 36" dia., bears N.35°W., 68 lks. dist., mkd. T32S R7W S3 BT.

BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #543, surveyed June, 1964 (DCSO records Vol. 33 Page(s) 13650-51)

The Sec. cor., monumented with the original corner tree, a Fir 12" dia., mkd. with healed blazes on the NE., SE., SW., and NW. sides, from which the original bearing trees:

- A Fir 44" dia., bears N.62°E., 90 lks., dist., mkd. T32S R7W S2 BT on bark blaze. (Rec. 97 lks.)
- A Fir 53" dia., bears S.16°E., 50 lks. dist., with illegible scribe marks on barks blaze. (Rec. S.22°E., 46 lks.)
- A Fir 55" dia., bears S.38°W., 94 lks. dist., mkd. T32S R7W S10 BT on bark blaze. (Rec. 89 lks.)
- A Fir 34" dia., bears N.25°W., 70 lks. dist., mkd. T2S R7W S3 BT on bark blaze. (Rec. N.35°W., 68 lks.)

Add a new bearing tree and reference monument

- A Fir 15" dia., bears S.65°E., 74 lks. dist., mkd. T32S R7W S11 BT.

An Iron post, 28" long, 2½" dia., set 24" in the ground, for a reference monument, bears N.62°E., 19½ lks. dist., with brass cap mkd. T32S R7W S2 RM 1964 and an arrow pointing to the corner.

The corner falls on spur, slopes S.80°E.

BLM resurvey by James E. Jelley, Cadastral Surveyor, under Group #1086, surveyed April/June 1982 - (DCSO records Vol. 46 Page(s) 17563)

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2, 3, 10 and 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

The Sec. cor., monumented with the original corner tree, a Fir 14" dia., mkd. with healed blazes on NE., SE., SW., and NW. faces, from which the remains of the original bearing trees:

A sawed Fir stump 40" dia., bears N.62°E., 90 lks. dist., with scribe marks BT visible on bark blaze.

A Fir 55" dia., bears S.16°E., 50 lks. dist., with fragmentary scribe marks visible on bark blaze.

A root hole bears S.38°W., 94 lks. dist., with a down Fir alongside, size indeterminate, no marks visible.

A Fir 40" dia., bears N.25°W., 70 lks. dist., with fragmentary scribe marks visible on bark blaze.

and a bearing tree and reference monument mkd. by Beck:

A Fir 17" dia., bears S.62°E., 74 lks. dist., with healed blaze. (Rec. S.65°E.)

An Iron post 2½" dia., firmly set, projecting 4" above ground, bears N.62°E., 19½ lks. dist., with brass cap mkd. T32S R7W S2 RM 1964 and an arrow pointing to the corner.

and a new bearing tree:

A Fir 10" dia., bears N.24°E., 24½ lks. dist., mkd. T32S R7W S2 BT.

No other suitable trees available within limits.

Survey by Howard Johnstone - For: Roseburg Resources - May 27, 1987 - C.S. File 63/26-7

Found - 40" Fir stump N.62°E., 59.4 ft. O.B.T., covered with metal.

55" Fir S.16°E., 33.0 ft. O.B.T. New stump.

40" Fir N.25°W., 46.2 ft. O.B.T. Bark scribes visible.

17" Fir S.62°E., 48.8 ft. 1964 BT. New stump.

10" Fir N.24°E., 16.2 ft. 1982 BT. Scribe visible.

Brass cap reference monument N.62°E., 12.9 ft. 1964. Good shape.

14" Fir Corner tree, original, down, broken off at ground.

New BTs -5" I.Cedar S.9°E., 48.0 ft. scribed T32S R7W S11 BT.

3½" D.Fir S.77°E., 24.8 ft. scribed X BT.

No trees available to the southwest. Secs. 2, 10 and 11 have been clear cut. Section 11, this past Spring.