

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 25 and 26

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 420 survey dated Sept 16 1881 (DCSO records Vol. 20 Page(s) 8715)

Set a Cedar ost 4 ft. long, 4" sq., 22" in the ground, marked 1/4 S on W. face, for the 1/4 sec. cor., from which
A Fir 40" dia., bears N.88°E., 32 lks. dist., mkd. 1/4 S BT
A Fir 40" dia., bears N.30°W., 52 lks. dist., mkd. 1/4 S BT

BLM remonumentation by Lynn M. Roseberry and Rollin D. Aanrud, Cadastral Surveyors, Under Group #'s 350 and 960, surveyed Aug/Sept. 1978 (DCSO records Vol. 42 Page(s) 16509-10)

The 1/4 sec.cor. of secs. 25 and 26, determined at record bearing from the original bearing trees:

A root hole bears N.88°E., 32 lks. dist., with a down and decayed Fir alongside 40" dia., no marks visible.

A sawed Fir stump 52" dia., bears N.30°W., 54 lks. dist., with scribe marks 1/4 S BT visible on bark blaze. (Rec. 52 lks.)

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. dia., 24 ins. in the ground, with brass cap marked T 32 S R 7 W

1/4
S 26*S 25
1978

from which new bearing trees

A Live Oak 12" dia., bears N.17°E., 37 lks. dist., mkd. 1/4 S25 BT.

A Sugar Pine 10" dia., bears S.24°W., 8 lks. dist., mkd. 1/4 S26 BT.

Mark Smalley - For: Roseburg Forest Products - 11/5/96 - C.S. File 65/8-19

Found - 1978 BLM Cad. IPBC.

40" Fir, N.30°W., 34.3' - stump.

12" Live Oak N.17°E., 24.4' - 13", good cond. part. healed face.

10" S.Pine, S24°W., 5.3' - 13" Good healed face - 2 BRNGS. on tag, N.29°E., & N.24°E.

New BTs- 10" Laurel, N.12°W., 48.5', scribed E 1/4 S26 BT"

15" S.Pine, N.36°W., 69.6', scribed E 1/4 S26 BT"

Note - Corner about 70' west of Rd. - Flush in loose shale.

continued next page

TOWNSHIP 32 RANGE 07 POINT IDENTIFIER # 600240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 25 and 26

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Ron Quimby - Crew: J. Leonard and N. Fromdahl - 1/2014 - C.S.
File 65/82-5

Found - BLM brass cap
15" Live Oak N.17°E., 24.7 ft. good scar.
52" Fir stump N.30°W., 34.3 badly burnt.
A badly burnt snag S.24°W., 5.3 ft. (4' tall)
New - A 8" Live Oak S.14°W., 7.4 ft. scribed ¼ S26 BT
Note - Corner is approx. 70' west of road. Area burnt
8/2013.
Compass decl. 15½°E.