

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 6 & 7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Richmond S. Dickerson, Deputy Surveyor under contract #474, dated May 10, 1883 - (DCSO records Vol. 21 Page(s) 8834-5)

Set a stone 14x12x10", 10" in the ground marked ¼ on N side for the ¼ sec. cor., from which

A laurel, 8" dia., bears N.16°E., 14 lks., mkd: ¼ S BT.

A laurel, 5" dia., bears S.42°W., 13 lks., mkd: ¼ S BT.

BLM dependent resurvey by Lynn M. Roseberry and Rollin D. Aanrud, Cadastral Surveyors, Group #821 & 876, surveyed July 1973/July 1975 - (DCSO records Vol. 40 Page(s) 15997)

Point for the ¼ sec. cor. of secs. 6 & 7, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 22" in the ground with brass cap marked:

T32S R8W

¼ $\frac{S\ 6}{S\ 7}$

1975

from which

A fir, 6" dia., bears N.28°W., 52½ lks., mkd: ¼ S6 BT.

A fir, 54" dia., bears S.20°E., 40½ lks., mkd: ¼ S7 BT.

Raymond Brown, LS #2391 - May 23, 1991 - C.S. File 63/129-10

Found - 1975 BLM brass cap in good condition

An orig. 6" now 12" D.Fir bears N.28°W., 34.66 ft. with healed double blaze in good shape, Added metal tag.

An orig. 54" now 54" D.Fir Stump, 3 ft. tall bears S.20°E., 26.73 with partly healed blaze, some scribing visible. Stump too short and damaged for capping, has metal tag.

Set - At corner, placed 6 ft. tall steel fence post, set 18" into ground, 1 ft southwest of corner.

New BTs- A D.Fir, 4" dia. bears N.57°E., 39.0 ft. mkd. "¼ S6 BT" with tag.

A Laurel, 5" dia. bears S.71°E., 35.6 ft. mkd. "¼ S7 BT" with tag.

A Tan Oak, 5" dia. bears S.54°W., 11.2 ft. mkd. "¼ S7 BT" with tag.

Found existing boundary tree: A Chinquapin, 16" dia. bears S.89°E., 29.9 ft. has line blaze marks & metal boundary tag.

Fd. brass cap & 3 BTs by D.Edwards, fd steel post 1 ft SW - 3/2011 - M162-26