

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 5 & 6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Richmond S. Dickerson, Deputy Surveyor under contract #474, dated May 10, 1883 - (DCSO records Vol. 21 Page(s) 8835-6)

Set a dogwood post 3 ft. long, 3" sq., 20" I the ground marked ¼ S on the W side for the ¼ sec. cor., from which
A live oak, 12" dia., bears East, 29 lks., mkd: ¼ S BT
A live oak, 6" dia., bears S.45°W., 27 lks., mkd: ¼ S BT.

Lorne Swearingen - For: The Robert Dollar Co. - Oct. 1960 - C.S. file 51/63-8

Found to be missing. One orig. BT remains with scribing visible but the tree (12" Tan Oak) is nearly rotted down. I set a 7/8"x30" hex drill steel driven 20" in the ground for the corner.
New BTs- 8" Fir N.30°E., 18.3 ft., scribed S 5 ¼ S 4186 BT.
22" Fir S.52½°W., 37.2 ft. scribed S 6 ¼ S 4186 BT.

BLM dependent resurvey by Lynn M. Roseberry and Rollin D. Aanrud, Cadastral Surveyors, Group #821 & 876, surveyed July 1973/July 1975 - (DCSO records Vol. 40 Page(s) 15998-9)

The ¼ sec. cor. of secs. 5 & 6, perpetuated and recorded by Lorne Swearingen in 1960, monumented with a steel rod, 7/8" dia., firmly set, projecting 10" above ground, from which the remaining orig. BT:
A tan oak, 15" dia., bears East, 29 lks., with fragmentary scribe marks visible on opened burned blaze. (Rec. live oak)
and BTs mkd. by Swearingen
A fir, 12" dia., bears N.32°E., 28 lks., with healed double blaze.
A fir, 22" dia., bears S.54¾°W., 56½ lks., with healed double blaze.
At the corner point
Set an iron post, 28" long, 2½" dia., 24" in the ground, directly over steel rod, with brass cap marked:
T32S R8W
¼
S 6|S 5
1975

Fd. brass cap & 3 BTs by D.Edwards, set 6 ft. steel post 2' N.9°E. - 3/2011 - M162-26