

TOWNSHIP 32 RANGE 08 POINT IDENTIFIER # 240600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 5 & 8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Richmond S. Dickerson, Deputy Surveyor under contract #474, dated May 10, 1883 - (DCSO records Vol. 21 Page(s) 8833-4)

Set a laurel post 3 ft. long, 3" sq., 20" in the ground marked ¼S on N side for the ¼ sec. cor. from which
A laurel, 10" dia., bears S.85°E., 10 lks., mkd: ¼ S BT.
A laurel, 10" dia., bears N.85°W., 11 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - John M. Powell - May 1968 - C.S. File 54/65

Reported as not found
Found blaze east, west line & about approx. corner. All trees have been cut into.

BLM dependent resurvey by Lynn M. Roseberry and Rollin D. Aanrud, Cadastral Surveyors, Group #821 & 876, surveyed July 1973/July 1975 - (DCSO records Vol. 40 Page(s) 15995-6)

Point for the ¼ sec. cor. of secs. 5 & 8, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 24" in the ground with brass cap marked:

T32S R8W
¼ $\frac{S \ 5}{S \ 8}$
1975

from which
A fir, 24" dia., bears N.13°W., 80 lks., mkd: ¼ S5 BT.
A fir, 12" dia., bears S.53°E., 42½ lks., mkd: ¼ S8 BT.

Ron Quimby - For: Plum Creek Timber Co. - 4/2016 - M171-9

Found - BLM brass cap per July 1973/July 1975 BLM dependent resurvey group # 821 & 876
39" Fir N.13°W., 52.8' fully healed scribe
18" Fir stump 2' tall S.53°E., 28.1' fully healed scribe cut in half.

New BTs- 9" chinquapin N.35°E., 9.1' scribed "¼ S5 BT"
9" chinquapin S.40°E., 13.7' scribed "¼ S8 BT"
6" chinquapin S.21°W., 14.3' scribed "¼ S8 BT"