

PRIMARY CORNER DESCRIPTION Cor. Secs. 28, 29, 32, & 33

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Richmond S. Dickerson, Deputy Surveyor under contract #474, dated May 10, 1883 - (DCSO records Vol. 21 Page(s) 8812-3)

-
- Set a live Oak post 4 ft. long, 4" sq., 24" in the ground for the cor. to secs. 28, 29, 32, & 33, mkd. T32S R8W S28 on NE, S33 on SE, S32 on SW, and S29 on NW, faces also 4 notches on the E, and 1 notch on S angles of same, and from which
 - A laurel, 8" dia., bears N.74°E., 71 lks., mkd: T32S R8W S28 BT.
 - A laurel, 10" dia., bears S.84°E., 60 lks., mkd: T32S R8W S33 BT.
 - A live oak, 5" dia., bears S.70°W., 21 lks., mkd: T32S R8W S32 BT.
 - A sugar pine, 32" dia., bears N.31°W., 48 lks., mkd: T32S R8W S29 BT.

Douglas Co. Surveyors Office - John M. Powell - May 1968 - C.S. File 54/65-4

Reported as not found.
Found large 54" pine with very old cruisers marks & location tag squared stake at cor., good N-S-E-W ines. Cut into pine with no results.

Robert M Thompson, LS#1358 - For: Boise Cascade Timber Lands of Oregon - Oct. 21, 1983 - M 95-33 & C.S. 58/275-3(N)

-
- Found - One OBT, 56" sugar pine, N.31°W., 31.7 ft., large face chopped out 12" deep, previous reported bark scribe destroyed. See narrative in C.S. 58/275-3 for corroborating evidence.
 - Set - 5/8" I. Rod at record position 30" long with yellow cap mkd: "Thompson PLS 1358"
 - New - Scribed "T32S R8W S(#)¹³⁵⁸ BT" on the following BTs
 - 7" tan Oak, S.61½°W., 24.8 ft.
 - 7" tan Oak, N.48°W., 30.7 ft.
 - 6" madrone, N.52°E., 26.6 ft.
 - 26" S.Pine, S.28°E., 21.1 ft.

Ron Quimby - Crew: N. Fromdahl, D. Manring, & R. Olsen - 10/2014 - C.S. File 65/86-28

-
- Found - 5/8" iron rod.
 - 60" S.Pine N.31°W., 31.7 chopped out face.
 - 10" Tan Oak S.61°W., 24.8 legible scribes.
 - 10" Tan Oak N.48°W., 30.7 good scar.
 - 6" Madrone N.52°E., 26.6 down
- continued next pg

TOWNSHIP 32 RANGE 08 POINT IDENTIFIER # 300200

PRIMARY CORNER DESCRIPTION Cor. Secs. 28, 29, 32, & 33

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

30" S.Pine S.28°E., 21.1 good scar.
Unrecorded 27" Fir S.82°E., 16.9 healed scar.
Compass decl. 15½°E.