

TOWNSHIP 32 RANGE 08 POINT IDENTIFIER # 300640

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 4 & 5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Richmond S. Dickerson, Deputy Surveyor under contract #474, dated May 10, 1883 - (DCSO records Vol. 21 Page(s) 8821)

A chinquapin, 6" dia., which I marked $\frac{1}{4}$ S on W side for the $\frac{1}{4}$ sec. cor., from which

A fir, 24" dia., bears S.10°E., 6 lks., mkd: $\frac{1}{4}$ S BT.
A fir, 6" dia., bears N.10°W., 31 lks., mkd: $\frac{1}{4}$ S BT.

Douglas Co. Surveyors Office - John M. Powell - April 1968 - C.S. File 54/65-33

Reported as not found.
Had good line & 1 good call on creek of 396.0' area in old burn.

BLM dependent resurvey by Lynn M. Roseberry and Rollin D. Aanrud, Cadastral Surveyors, Group #821 & 876, surveyed July 1973/July 1975 - (DCSO records Vol. 40 Page(s) 15993-4)

The $\frac{1}{4}$ sec. cor. of secs. 4 & 5, determined at record bearing & distance from the remaining orig. BT:

A fir, 33" dia., bears S.10°E., 6 lks., with scribe marks $\frac{1}{4}$ S visible on burned bark blaze.

At the corner point

Set an iron post, 28" long, 2 $\frac{1}{2}$ " dia., 22" in the ground, with brass cap marked:

T32S R8W
 $\frac{1}{4}$
S 5|S 4
1975

from which a new BT

A fir, 13" dia., bears N.86°W., 67 lks., mkd: $\frac{1}{4}$ S5 BT.

Ron Quimby - For: Rsbg Resources Co. - 3/2002 - M139-64 A&B

Found - BLM brass cap, properly marked.

36" Fir S.10°E, 4.0 ft. (Healed)

18" Fir N.86°W, 44.2 ft. (Healed)

New BTs- 10" Fir N.27°W 15.3 ft. scribed: T32S R8W S5 BT

8" Fir S.80°E 23.7 ft. scribed: "X" at breast high & BT at base.