

TOWNSHIP 32 RANGE 08 POINT IDENTIFIER # 440500

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 10 & 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>GLO survey by Richmond S. Dickerson, Deputy Surveyor under contract # 474 dated May 10, 1883 (DCSO records Vol. 21 Page(s) 8809)</p> <p>-----</p> <p>Set a stone 16x12x8, 12" in the ground marked <math>\frac{1}{4}</math> on N side, for <math>\frac{1}{4}</math> sec. cor, from which</p> <p>    A fir, 6" dia., bears N.17°E., 43 lks., mkd: <math>\frac{1}{4}</math> S BT.</p> <p>    A fir, 8" dia., bears S.72°W., 21 lks., mkd: <math>\frac{1}{4}</math> S BT.</p>
<p>Douglas Co. Surveyors Office - John Powell - 4/1968 - C.S. file 54/65-5</p> <p>-----</p> <p>Reported as not found</p> <p>2 small firs 6"-8"BTs. Good call on creek 198.0 from cor. Good E-W line.</p> <p>All trees in general area have been opened with no results.</p>
<p>Douglas Co. Surveyors Office - Stephen J. Flause - John Pike - 6/15/2005 - C.S. File 67/10-31</p> <p>-----</p> <p>Searched for, not found.</p> <p>All trees in search area that were proper size were previously opened.</p>
<p>David Edwards - For: Roseburg Resources - 8/2005 - M 148-31</p> <p>-----</p> <p>Set - 5/8"x30" steel rebar with 2<math>\frac{1}{2}</math>" alum cap mkd: "ROSEBURG RESOURCES LS2339 2005"</p> <p>    6" Fir S.75°E., 26.3'</p> <p>    8" Fir S.15°W., 17.46'</p> <p>    6" Live Oak (double blazed) S.34°W., 13.8'</p> <p>    10" Sugar Pine N.31°W., 35.8'</p>
<p> </p>