

PRIMARY CORNER DESCRIPTION Cor. Secs. 22, 23, 26, & 27

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Richmond S. Dickerson, Deputy Surveyor under contract #474, dated May 10, 1883 - (DCSO records Vol. 21 Page(s) 8796)

Set a fir post, 4 ft. long, 4" sq., 24" in the ground for the cor. to secs. 22, 23, 26, & 27 and marked T32S R8W S23 on NE, S26 on SE, S27 on SW, and S22 on NW faces, also 2 notches on the S and 2 notches on the East angle of same, and from which

- An Alder, 8" dia., bears N.20°E., 28 lks., mkd: T32S R8W S23 BT.
- An Alder, 10" dia., bears S.50°E., 33 lks., mkd: T32S R8W S26 BT.
- A fir, 10" dia., bears S.35°W., 18 lks., mkd: T32S R8W S27 BT.
- A maple, 10" dia., bears N.12°W., 44 lks., mkd: T32S R8W S22 BT.

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & W. Penley - April 1968 - C.S. File 54/65-37

Found - 10" now 13" Maple, N.12°W., 29.0 ft., tree has been opened, face burnt, but fragmentary scribing visible.

- 10" D.Fir, now gone, but bearing & dist. to old stump hole good.
- 2 Alder BTs not found.

Call on creek 19.0 ft. E; at this time find to be about 9.0 t.

Set brass cap at cor. mkd: County Surveyors T32S R8W
Office S 22 | S 23
1968 S 27 | S 26

New BTs- 10" Maple S.19°E., 15.4 ft. mkd: T32S R8W S26 CS BT.
31" D.Fir S.44°W., 21.9 ft. mkd: T32S R8W S27 CS BT.
12" L.Oak N.34°E., 61.4 ft. mkd: T32S R8W S23 CS BT.
13" L.Oak West, 28.5 ft., mkd: T32S R8W S22 CS BT.

Ron Quimby - Crew: J. Leonard and N. Fromdahl - 1/2014 - C.S. File 65/82-14

Found - Brass cap on iron pipe (properly mkd)
40" Fir S.44°W., 21.9 ft. good scar.
16" L.Oak West 28.5 ft. good scar.
14" L.Oak N.34°E., 61.4 ft. good scar.

New - 8" L.Oak S.68°E., 33.3 ft. scribed T32S R8W S26

Note - Corner is approx. 10' west of creek approx. 150' south of Rd. Area badly burnt 7/2013.

TOWNSHIP 32 RANGE 08 POINT IDENTIFIER # 500300

PRIMARY CORNER DESCRIPTION Cor. Secs. 22, 23, 26, & 27

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM dependent resurvey by Kevin G Mulder, Cadastral Surveyor, under Group No. 2741; Surveyed March/April 2014 - (DCSO records Vol. 58 Page(s) 23258)

The cor. of secs. 22, 23, 26, & 27, perpetuated from original evidence no longer in existence, by the Douglas Co Surveyor's Office in 1968, under C.S. 54/65, and further perpetuated by Quimby, PLS No. 1654, in 2014; monumented with an iron post, 1½" dia., firmly set, projecting 8" above the ground, with brass cap (properly) mkd.

from which the remains of BTs mkd. by the Douglas County Surveyor's Office

A live oak snag, 12" dia., bears N.33°E., 60.1 ft., with a healed lower blaze and scribe marks S visible on partially healed upper blaze.

A fir, 38" dia., bears S.43½°W., 21.0 ft., with a healed blaze.

A live oak snag, 12" dia., bears N.86°W., 27.5 ft., with a healed blaze.

and a bearing tree mkd. by Quimby

A live oak, 8" dia., bears S.69°E., 33.3 ft., with scribe marks T32S R8W S26 visible on partially healed blaze.

and new bearing trees

A fir, 12" dia., bears N.69°E., 27.2 ft., mkd. T32S R8W S23 BT.

A fir, 5" dia., bears N.22¼°W., 31.1 ft., mkd. X at breast height and BT at the base.

Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center.

NAD 1983 (2011)

Latitude: 42°46'03.81"N Longitude: 123°37'16.20"W