

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 10 & 11

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Richmond S. Dickerson, Deputy Surveyor under contract #474, dated May 10, 1883 - (DCSO records Vol. 21 Page(s) 8800)

-----  
A Laurel, 5" dia., which I marked  $\frac{1}{4}$  S on W side, for the  $\frac{1}{4}$  sec. cor. and from which

A laurel, 5" dia., bears S.75°E., 20 lks., mkd:  $\frac{1}{4}$  S BT.  
A laurel, 5" dia., bears S.80°W., 5 lks., mkd:  $\frac{1}{4}$  S BT.

Douglas Co. Surveyors Office - John Powell - 5/1968 - C.S. file 54/65-3

-----  
Reported as not found.  
This cor. falls in large cleared area on steep hillside. Cleared for old logging Rd. Cor. had 3-5" Laurels, call on creek of 400.00

BLM dependent resurvey by Lynn M. Roseberry and Rollin D. Aanrud, Cadastral Surveyors, Group #821 & 876, surveyed July 1973/July 1975 - (DCSO records Vol. 40 Page(s) 15986)

-----  
Point for the  $\frac{1}{4}$  sec. cor. of secs. 10 & 11, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28 long, 2 $\frac{1}{2}$ " dia., 24" in the ground with brass cap marked:

T32S R8W  
 $\frac{1}{4}$   
S 10 | S 11  
1975

from which

A fir, 17" dia., bears N.36°E., 92 lks., mkd:  $\frac{1}{4}$  S11 BT.  
A live oak, 10" dia., bears S.47°W., 28 lks. mkd:  $\frac{1}{4}$  S10 BT

Fd. Ok by D. Edwards - 8/2005 - M148-31

Ron Quimby - Crew: N. Fromdahl & R. Olsen - 7/2014 - C.S. File 65/82-57

-----  
Found - BLM Brass cap (cap mkd  $\frac{1}{4}$  S1 | S 11) (S1 not S10)  
16" Live oak S.47°W., 18.5 ft. good scar.  
New - 5" madrone N.33°E., 6.0 ft. scribed  $\frac{1}{4}$  S11 BT.  
8" Fir S.71°E., 27.7 ft. scribed  $\frac{1}{4}$  S11 BT.  
10" Live Oak N.44°W., 23.6 ft. scribed  $\frac{1}{4}$  S10 BT.  
Compass decl. 15 $\frac{1}{2}$ °E.