

TOWNSHIP 32 RANGE 08 POINT IDENTIFIER # 600340

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 23 & 24

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Richmond S. Dickerson, Deputy Surveyor under contract #474, dated May 10, 1883 - (DCSO records Vol. 21 Page(s) 8786)

Set a laurel 3½ ft. long, 3" sq. 20" in the ground for the ¼ sec. cor. marked ¼ S on the W face and from which
A fir, 16" dia., bears N.65°E., 82 lks., mkd: ¼ S BT.
A fir, 8" dia., bears S.62°W., 97 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & W. Penley - April 1968 - C.S. File 54/65-43

Found - 8", now 26" D.Fir, S.62°W. 64.0 ft., opened for scribe "1/"
No trace of NE BT.
Set - Brass Cap at Cor. mkd: County Surveyors T32S R8W
Office ¼ S 23|S 24
1968
New BTs- 16" D.Fir N.76°W., 39.2 ft. mkd. ¼ S23 CS BT.
12" D.Fir S.51°E., 30.0 ft. mkd. ¼ S24 CS BT.

Ron Quimby - Crew: J. Leonard and N. Fromdahl - 11/2013 - C.S. File 65/80-56

Condition report only
Found - County Surveyors Office Brass cap, (properly mkd)
18" fir N.51°E., 30.0 ft. (Sec. S.51°E.) good scar.
24" fir N.76°W., 39.2 ft., good scar.
28" fir S.62°W., 64.0 ft. good scar.
Note - Corner is approx. 150' west of road.
Area burnt 7/2013
Dec. 15°