

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Richmond S. Dickerson, Deputy Surveyor under contract #474, dated May 10, 1883 - (DCSO records Vol. 21 Page(s) 8786)

-----

Set a chinquapin post, 4 ft. long, 4" sq., 24" in the ground for cor. to secs. 13, 14, 23, & 24, marked T32S R8W S13 on NE, S24 on SE, S23 on SW, and S14 on NW, with 3 notches on S & 1 notch on E edges of same and from which

- A laurel, 10" dia., bears N.70°E., 40 lks., mkd: T32S R8W S13 BT.
- A laurel, 6" dia., bears S.40°E., 38 lks., mkd: T32S R8W S24 BT.
- A fir, 40" dia., bears S.89°W., 29 lks., mkd: T32S R8W S23 BT.
- A laurel, 6" dia., bears N.26°W., 85 lks., mkd: T32S R8W S14 BT.

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & W. Penley - April 1968 - C.S. File 54/65-48

-----

Found - Orig. 40", now 60" D.Fir, S.89°W., 19.1 ft., bark scribe visible, "T32S R8W S23, faint BT"  
 Orig. 10" Laurel, now dead, N.70°E., 26.4 ft., rotted out.  
 No trace of SE or NW BTs.

Set - Brass Cap at Cor. mkd: County Surveyors T32S R8W  
 Office S 14 | S 13  
 1968 S 23 | S 24

New BTs- 10" Laurel N.36°W., 33.6 ft. mkd. T32S R8W S14 CS BT  
 16" Tan Oak S.12°W. 14.9 ft. mkd. T32S R8W S23 CS BT  
 48" D.Fir S.71°E., 41.4 ft. mkd. T32S R8W S24 CS BT.  
 No good trees reasonable to NE

BLM dependent resurvey by Lynn M. Roseberry and Rollin D. Aanrud, Cadastral Surveyors, Group #821 & 876, surveyed July 1973/July 1975 - (DCSO records Vol. 40 Page(s) 15975)

-----

The cor of secs. 13, 14, 23, and 24, perpetuated and recorded by Powell, in 1968; monumented with an iron pipe, 1" dia., firmly set, projecting 12" above ground, with brass cap (properly) mkd from which the remains of the original bearing trees

- A madrone snag. 15" dia., bears N.70°E., 40 lks., no marks visible on decayed blaze.
- A fir, 67" dia., bears S.89°W., 31 lks., with scribe marks T32S R8W S23 visible on bark blaze. (Record, 29 lks.)

and the remains of bearing trees mkd. by Powell  
 continued next page

TOWNSHIP 32 RANGE 08 POINT IDENTIFIER # 600400

PRIMARY CORNER DESCRIPTION Cor. Secs. 13, 14, 23, & 24

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

A sawed fir stump, 48" dia., bears S.71°E., 63 lks., with scribe marks T32S R8W CS visible on partially healed blaze.

A tan oak, 18" dia., bears S.12°W., 22½ lks., with scribe marks T32S R8W S23 BT visible on partially healed double blaze.

A madrone, 12" dia., bears N.36°W., 50½ lks., with scribe marks T32S R8W S14 CS BT visible on partially healed double blaze.

and a new bearing tree

A fir, 40" dia. bears N.61°E., 97 lks mkd. T32S R8W S13 BT

Ron Quimby - Crew: J. Leonard and N. Fromdahl - 11/2013 - C.S. File 65/80-58

-----

Found - County Surveyors Office Brass cap, (properly mkd)  
6' tall fir stump 70" S.89°W., 20.5 ft., burnt  
48" fir stump S.71°W., 41.6 ft. burnt scar.  
22" tan oak S.12°W., 14.9 ft. good scar.  
16" madrona N.36°W., 33.3 ft. good scar.  
46" fir N.61°E., 64.0 ft. burnt.

New - Set alum. post 2.0 east and 2.0 south.

Note - Area burnt 8/2013  
Dec. 15°