

TOWNSHIP 32 RANGE 08 POINT IDENTIFIER # 600520

PRIMARY CORNER DESCRIPTION S 1/16 Secs. 11 & 12

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM dependent resurvey by Lynn M. Roseberry and Rollin D. Aanrud, Cadastral Surveyors, Group #821 & 876, surveyed July 1973/July 1975 - (DCSO records Vol. 40 Page(s) 15978)

Point for the S1/16 sec. cor. of secs. 11 & 12
Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:
S 1/16
S 11|S 12
1975

from which
A sugar pine, 15" dia., bears N.40¾°E., 110 lks., mkd: S 1/16 S12 BT.
A fir, 23" dia. bears N.87½°W., 174 lks mkd: S 1/16 S11 BT

Raymond Brown - May 23, 1991 - C.S. file 63/129

Found - BLM brass cap in good condition.
15" Sugar pine now 22", bears N.40°45'E., 72.60 ft. with healed blaze, in good shape. (orig. 1975 tree)
23" D.Fir now 28" dia. stump, 6'6" tall, bears N.87°30'W., 115.30 ft. to center of stump, with healed blaze. (orig. 1975 tree)
Set - At corner, placed 6 ft. tall steel fence post, set 18" into ground, 1 ft. west of corner.
New - A Madrona, 8" dia. bears S.54°W., 18.62 ft. mkd. "S1/16 S11 BT"
Found existing fir stump has been debarked, treated with a copper napthanate solution and will be capped with galvanized metal by 7/01/91.

Ronald Quimby, Fromdahl, Olsen - 8/2014 - CS 65/86-4

Found - BLM brass cap
32" Sugar pine N.41°E. 72.6' good scar.
12" Madrone S.64°W. 18.6ft vis scribe.
28"x6' tall stump N.87°W. 115.3ft badly burnt.
6' post 1° west
Comments - Area burnt 7/2013
Compass decl. 15½°E.

Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and Jeff Lorsung - 4/14/2025 - C.S. File 67/60-19

Found - ¾" BLM brass cap under fallen Madrone. Not buried. Up 3".
32" sugar pine N.40¾°E. 72.6 ft healed blaze. Add ¾" mag nail right side center.

Continued next page

TOWNSHIP 32 RANGE 08 POINT IDENTIFIER # 600520

PRIMARY CORNER DESCRIPTION S 1/16 Secs. 11 & 12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Burnt very rotten 9"x6½' D.fir stump N.87½°W. 115.3'.
12" madronea S.54°W. 18.6 ft partly healed double
blaze. Illegible scribes. Add 3½" mag nail right
side center.
Compass decl. 14½°E.
Lat 42°48'01.23801"N Long 123°36'11.81587"W

2