

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 1 & 12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Richmond S. Dickerson, Deputy Surveyor under contract #474, dated May 10, 1883 - (DCSO records Vol. 21 Page(s) 8792)

A live oak, 10" dia., which I mark ¼ S on the N side for the ¼ sec. cor. and from which

A laurel, 5" dia., bears N.65°E., 24 lks., mkd: ¼ S BT.

A live oak, 18" dia., bears S.54°E., 79 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - John Powell - 3/1968 - C.S. File 54/65-9

Reported as not found.

Found probable cor. tree. Also correct bearing & dist. to L.Oak with very old axe work. Also hit bearing & dist. to where a laurel has been but burnt. All trees rotted out, no evidence for renewal.

BLM dependent resurvey by Lynn M. Roseberry and Rollin D. Aanrud, Cadastral Surveyors, Group #821 & 876, surveyed July 1973/July 1975 - (DCSO records Vol. 40 Page(s) 15980

The ¼ sec. cor. of secs. 1 & 12, monumented with the orig. corner tree, a hollow live oak, 20" dia., no marks visible on decayed N. face, from which

A madrone root crown, size indeterminate, bears N.65°E., 24 lks.

A hollow live oak, 17" dia., bears S.54°E., 79 lks., no marks visible.

At the corner point

Set an iron post, 28" long, 2½" dia., 20" in the ground, in center of orig. corner tree, with brass cap marked:

T32S R8W
 ¼ $\frac{S \ 1}{S \ 12}$
 1975

from which new BTs

A live oak, 9" dia., bears N.10°E., 26 lks., mkd: ¼ S1 BT.

A fir, 12" dia., bears S.56°E., 56½ lks., mkd: ¼ S12 BT.

FD BC & 2 BTs 4/1980 by Howard Johnstone, M83-25

FD BC & 2 BTs 3/2013 by D. Edwards, M164-73 - Set 6 ft. steel post 2' West.

continued next page

TOWNSHIP 32 RANGE 08 POINT IDENTIFIER # 640600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 1 & 12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Ron Quimby - Crew: J. Leonard & N. Fromdahl - 11/2013 - C.S.
File 65/80-43

Condition report only

Found - BLM brass cap (properly mkd)
12" Live Oak N.10°E., 17.2 ft. vis. scribe.
16" fir S.56°E., 37.3 ft. vis. scribe.

New - Re-tag trees

Note - Cor. is approx. 150' east of railroad area burnt
7/2013
Compass decl. 15°E.

BLM resurvey by Brandon G Courtright, Cadastral Surveyor,
under Group No. 2754, surveyed May/July 2014 - (DCSO records,
Vol. 58 page(s) 23374)

The ¼ sec. cor. of secs. 1 and 12, monumented with an iron
post, 2½" dia., firmly set, projecting 5" above ground, in
the center of the original cor. tree (a hollow live oak, 24"
dia.) with brass cap (properly) mkd.
from which the remains of the bearing trees mkd. by Roseberry
and Aanrud in 1973-75

A live oak, 12" dia., bears N.10°E., 17.2 ft., with scribe
marks S1 BT visible on partially healed blaze.

A fir stump, 6 ft. high, 18" dia., bears S.56°E., 37.3
ft., with a healed blaze.

and a new bearing tree

A fir, 10" dia., bears S.50½°E., 40.6 ft., mkd. ¼ S12 BT.
From this cor., a point established by Edwards, PLS No. 2339,
in 2013, as a point on the sec. line bet. secs. 1 and 12,
bears S.89°25'31" W., 68.89 ft., monumented with an iron rod,
5/8" dia., firmly set, projecting 5" above ground, with alum.
cap (properly) mkd. ROSEBURG RESOURCES CO PROP COR LS2339
2013 and was not utilized for control in the course of this
survey.