

TOWNSHIP 32 RANGE 08 POINT IDENTIFIER # 700200

PRIMARY CORNER DESCRIPTION Sec cor for 25 & 36; 30 & 31 of T32-7

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by W.H. Byars, Deputy Surveyor under contract # 420 survey dated Sept 16 1881 (DCSO records Vol. 20 Page(s) 8707)

Marked a Fir tree, 28" dia., for the corner to secs. 25, 30, 31 and 36 marked T32S R7W S30 on NE.; S31 on SE.; S36 on SW.; and T32S R8W S25 on NW.; with one notch on South and five notches on North edges, from which

- A Fir 18" dia., bears N.68°E., 70 lks. mkd. T32S R7W S30 BT.
- A Fir 20" dia., bears S.70°E., 74 lks. mkd. T32S R7W S31 BT.
- A Fir 18" dia., bears S.10°W., 72 lks. mkd. T32S R8W S36 BT.
- A Fir 10" dia., bears N.82°W., 100 lks. mkd. T32S R8W S25 BT.

Cor. Fd. and used in GL0 survey by Richmond Dickerson, under Contract #474, May 1883 (DCSO records, Vol. 21 Page 8782)

Douglas Co. Surveyors Office - John M. Powell, Frank Jones, Joe Darby, crew - November 1967 - C.S. File 54/36-93

Found - 28" Corner Tree, now rotten stob.
Orig. 20" Fir now stob, S.70°E., 48.8 ft., no scribing.
Orig. 18" Fir, now burnt stub, S.10°W., 47.5 ft. bark scribe found, T3 R8W BT
Orig. 10" Fir, now stob, N.82°W., 66.0 ft., scribe marks but not legible.
Distances to bearing trees appear to be slope distances.

Set Brass cap at South edge of Corner tree stob mkd:

County Surveyors Office

R	T 32 S	R
8	S 25 S 30	7
W	S 36 S 31	W

1967

- New BTs -8" D.Fir, East 13.4 ft. mkd. T32S R7W S30 CS BT.
- 8" D.Fir S.78°E., 16.1 ft. mkd. T32S R7W S31 CS BT.
- 9" D.Fir N.34°W., 3.5 ft. mkd. T32S R8W S25 CS BT.
- 10" Laurel S.4°W., 25.2 ft. mkd. T32S R8W S36 CS BT.

This corner lies approx. 30 ft. South of high rock point.

Fd. OK, DCSO, J.Powell, March 1968, C.S. File 54/36-157

(Cont. Next Page)

TOWNSHIP 32 RANGE 08 POINT IDENTIFIER # 700200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 25 & 36; 30 & 31, T32-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Randall Smith, Stephen Flause, crew - Dec. 10, 1992 - C.S. File 64/35-4

Found - A 2½" dia. 1967 DCS0 brass cap on a 1¼" O.D. Iron pipe, protruding 18" above ground.
Orig. 18" now 20" dia., D.Fir stob with illegible bark scribing, bears S.10°W., 44.8 ft. (Rec. S.10°W., 47.5 ft.)
8" now 13" dia., D.Fir with a fully healed double blaze bears S.85½°E., 13.4 ft. (Rec. East, 13.4 ft.)
8" now 9" dia., D.Fir with a partially healed double blaze scribe marks visible, bears S.78°E., 15.0 ft. (Rec. S.78°E., 16.1 ft.)
9" now 13" dia., D.Fir with a fully healed double blaze bears N.34°W., 3.5 ft. (agrees w/rec)
10" now 10" dia., Madrone with a partially healed double blaze scribing visible "32S R8W S36 CS BT" bears S.4°W., 24.1 ft. (Rec. S.4°W., 25.2 ft.)

A mound of stone is added around base of DCS0 BC/IP. Brass cap protrudes 3" above 3 ft x 2 ft x 15" deep mound of stone. No new accessories.

Fd. OK - Bruce Shaner - 1/6/96 - M 123-17

Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and Jeff Lorsung - 4/24/2025 - C.S. File 67/60-22

Found - 2½" D.C.S.O. brass cap in mound of stone.
17" D.Fir S.85½°E. 13.4 ft fully healed double blaze
Add 3½" mag nail right side center.
10"x9' rotted D.Fir snag S.78°E. 15.0 ft. Almost healed double blaze. Add 3½" mag nail right side center.
17" D. Fir N.34°W. 3.5 ft fully healed double blaze.
Add 3½" mag nail right side center.
11" madrone S.4°W. 23.9 ft (Rec 24.1 ft) scribes visible on upper blaze. 32S R8W S36CS. Lower blaze healed. Add 3½" mag nail left side center.

Notes - Mon. is approx. 400 ft south of first switch back on Skull Creek Rd.

Mon. On rocky slope on regrowth oak/fir madrone.

Compass decl. 14½°E.

GED XT GPS postiton

Lat. 42.75414 N Long. 123.58342 W