

TOWNSHIP 32 RANGE 08 POINT IDENTIFIER # 700340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 24; and 19, T32-7

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars, Deputy Surveyor under contract # 420 survey dated Sept 16 1881 (DCSO records Vol. 20 Page(s) 8708)

-----  
Set a Fir post, 4 ft. long, 4" sq., marked ¼ S. on W. side, 18" in the ground for the ¼ sec. cor., from which  
A Pine 38" dia., bears S.70°E., 70 lks. mkd. ¼ S BT.  
A Fir 30" dia., bears N.85°W., 43 lks. mkd. ¼ S BT.

Douglas Co. Surveyors Office - John M. Powell and crew - Dec. 15, 1967 - C.S. File 54/36-160

-----  
Found - Orig. 38" Pine, now dead stob, S.70°E., 46.2 ft., old axe work, no scribing.  
Orig. 30" now 40" D.Fir, N.85°W., 28.4 ft., bark scribe visible, "¼S BT"

Set Brass cap at ¼ cor. mkd: County Surveyors Office

|   |               |   |
|---|---------------|---|
| R | T 32 S        | R |
| 8 | ¼ S 24   S 19 | 7 |
| W | 1967          | W |

New BTs -12" D.Fir N.24½°E., 27.7 ft. mkd. ¼ S19 CS BT.  
6" Y.Pine S.78°W., 26.2 ft. mkd. ¼ S24 CS BT.

This corner lies approx. 250 ft. South of old dead end logging road, location tag on road.

Fd. OK, M. Hull, Oct. 1990, M 111-4

Jerry Estabrook - For: Roseburg Resources Co. - 4/2003 - M142-2 & C.S. 65/45-25

-----  
Found - A 2½" brass cap on 1" iron pipe marked "T32S, R7W, R8W, ¼, S 19, 524, 1967".  
A 30" pine snag with tag bears S.70°E., 46.20' to face, original.  
A 36" fir stamped with tag bears N.85°W., 28.40' to face, original.  
A 21" fir with healed face and tag bears N.24°30"E 27.70', CS 54/36.  
A 12" pine with healed face and tag.  
New BTs- A 7" fir with face scribed "BT" with X chop and tag bears N.51°W., 14.80' to side center.  
A 12" madrone face scribed "T32S R7W S19 W ¼ BT" bears S.58°E., 20.50' to side center.

continued next page

TOWNSHIP 32 RANGE 08 POINT IDENTIFIER # 700340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 24; and 19, T32-7

|             |                   |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

BLM Dependent resurvey by Arthur R. Rambo, Cadastral Surveyor under Group No. 2179, surveyed July/Nov. 2007 - (DCSO records, Vol. 55 Page(s) 21601-2)

-----  
The ¼ sec. cor. of secs. 19 and 24, perpetuated by the Douglas County Surveyor's Office, in 1967, monumented with an iron post, 1" dia., firmly set, projecting 10" above the ground, with brass cap (properly) mkd.

from which the remains of the original bearing trees

A rotted pine stump, 30" dia., bears S.70°E., 47.7 ft., no marks visible. (Record, 46.2 ft.)

A sawed fir stump, 34" dia., bears N.85°W., 29.6 ft., no marks visible. (Record, 28.4 ft.)

and BTs mkd. by the Douglas County Surveyor's Office, in 1967

A fir, 22" dia. bears N.23½°E. 27.8 ft with a healed blaze

A pine snag, 12" dia., bears S.78°W., 26.2 ft., with a healed blaze.

and bearing trees mkd. by Estabrook, in 2003

A madrone, 14" dia., bears S.54°E., 20.5 ft., with scribe marks T32S R7W W¼ BT visible on open blaze.

A fir, 8" dia., bears N.48°W., 14.7 ft., with an X chopped into tree at breast height and scribe marks BT visible at base, on partially healed blaze.

DCSO-GIS Corner visitation - 1/28/2004 - Typed: 2/10/2011 - C.S. File 67/33-1

-----  
Monument - 2" IP/BC Comment - (needs) rehab

Fd. BC & accessories per rec. 12/11/2013 - R. Quimby M167-8