

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1 & 12; 6 & 7 of T32-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 420 survey dated Sept 16 1881 (DCSO records Vol. 20 Page(s) 8711)

Set a Cedar post 4½ ft. long, 4" in dia., 20" in the ground for the corner to secs. 1, 6, 7, and 12, marked T32S R7W S6 on NE. side; S7 on SE. side; S12 on SW. side; R8W S1 on NW. side; from which

- A Pine 45" dia., bears N.80°E., 6 lks. dist., mkd. T32S R7W S6 BT.
- A Pine 14" dia., bears S.50°E., 140 lks. dist., mkd. T32S R7W S7 BT.
- A Fir 22" dia., bears S.8°W., 66 lks. dist., mkd. T32S R8W S12 BT.
- A Fir 20" dia., bears N.45°W., 123 lks. dist., mkd. T32S R8W S1 BT.

Fd. and used in GLO survey by Dickerson, May 1883, (DCSO records, Vol. 21 Page 8791)

Douglas Co. Surveyors Office - John M. Powell, Frank Jones, W. Penley, crew - April 1968 - C.S. File 54/36

Found - Unrecorded 3/4" I.Pipe at sec. corner.
Orig. 22" D.Fir, now down, S.8°W., 43.5 ft., bark scribe visible.
Pine stump N.80°E., no evidence.

Set Brass cap at cor. mkd: County Surveyors Office
R T 32 S R
8 S 1 * S 6 7
W S 12* S 7 W
1968

- New BTs -8" Laurel S.41°E., 4.4 ft. mkd. T32S R7W S7 CS BT.
- 12" D.Fir S.42°W., 19.5 ft. mkd. T32S R8W S12 CS BT
- 10" D.Fir N.56°W., 14.0 ft. mkd. T32S R8W S1 CS BT.
- 12" D.Fir N.64°E., 38.0 ft. mkd. T32S R7W S6 CS BT.

Fd. and used in BLM resurvey by Roseberry and Aanrud, Group #'s 821 and 876, surveyed Aug. 1973/Oct. 1975 (DCSO records, Vol. 40 Page 15974) AND also by Roseberry and Aanrud in 1978, (DCSO records, Vol. 42 Page 16508)

Fd. OK, by Max Hull, Sept. 1989, C.S. File 63/24 and M 108-69

continued next page

TOWNSHIP 32 RANGE 08 POINT IDENTIFIER # 700600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1 & 12; 6 & 7 of T32-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Ron Quimby - Crew: J. Leonard & N. Fromdahl - 11/2013 - C.S.
File 65/80-42

Condition report only

Found - DCSO brass cap (properly mkd)
 20" Fir N.64°E 38.0, healed face.
 20" Fir N.56°W., 14.0, healed face.
 26" Fir S.42°W., 19.5, healed face.
 14" madrona S.41°E., 4.4, vis. scribes

Set - 6' alum. post 2.0 west.
 Re-tag trees

Note - Area burnt 7/2013
 Compass decl. 15°E.