

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. H. Byars, Deputy Surveyor, under Contract #727, dated Dec. 20, 1900 - (DCSO records Vol. 19 Page(s) 8169)

Mark a Chinquapin 5" dia., T31S S35 on NE.; R9W S34 on NW.; and 2 notches on E. and four notches on W. sides, for the cor. of secs. 34 and 35, from which
A Laurel 5" dia. bears N.20°E. 34 lks. mkd T31S R9W S35 BT
A Laurel 5" dia. bears N.8°W. 84 lks. mkd. T31S R9W S34 BT

GLO Resurvey by Fred Mensch and Gerald A. Sorrels, Surveyors under Special Instructions, Group #35, dated Dec. 22, 1916 - (DCSO records Vol. 29 Page(s) 12189-90)

Intersect the cor. of secs. 34 and 35, which is a Chinquapin tree, 5" dia., killed by fire, fallen and partly burned; both bearing trees have been destroyed by fire. I perpetuate this cor. as follows: alongside the stump of the old cor. tree, Set an Iron post 3 ft. long, 2" dia., 24" in the ground for cor. of secs. 34 and 35, T31S R9W only, with brass cap mkd.

T31S	R9W
S 34	S 35
1917	

from which

A Fir 20" dia., bears N.1°30'E., 500 lks. dist., T31S R9W S35 BT. (New BT)
A Fir 36" dia., bears N.5°W., 449 lks. dist. mkd. T32S R9W S34 BT. (New BT)

Douglas Co. Surveyors Office - John M. Powell, and crew - March/April 1967 - C.S. File 54/32-69

Found - GLO brass cap at sec. cor., properly mkd. in 1917. 20" now 33" D.Fir N.1½°E., 330.0 ft shows good scar. 36" now 40" D.Fir snag, N.5½°W., 329.4 ft., shows good scar.

Did not open these trees, being convinced they are right by surrounding trees which are small & other badly burnt stumps. New BTs- 10" D.Fir N.40°W., 27.0 ft. mkd. T31S R9W S34 CSBT
10" D.Fir N.37°E., 32.7 ft. mkd. T31S R9W S35 CS BT

Tony Hostetter - For: Plum Creek. Co. - Dec 2010 - M161-80

Found - 1917 GLO brass cap and BT as described by Douglas County Surveyor in 1967 CS 54/32.

continued next page

TOWNSHIP 32 RANGE 09 POINT IDENTIFIER # 459700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 34 and 35 only, T31-9

Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____

BLM dependent resurvey by Kevin G Mulder, Cadastral Surveyor, under Group No. 2862; Surveyed Nov./Dec. 2016 - (DCSO records Vol. 59 Page(s) 23581-2)

The cor. of secs. 34 and 35 only, perpetuated by the Douglas County Surveyor's Office in 1967, monumented with an iron post, 2" dia., firmly set, projecting 13" above the ground, with brass cap (properly) mkd.

from which a bearing tree mkd. by Mensch and Sorrels in 1917

A fir, 35" dia., bears N.1¼°E., 328.9 ft., with a healed blaze. (Record, N.1½°E., 330.0 ft.)

and BTs mkd. by the Douglas County Surveyor's Office

A fir, 23" dia., bears N.35½°E., 32.4 ft., with a healed blaze.

A fir, 24" dia., bears N.40¼°W., 26.9 ft., with a healed blaze.

NAD 1983 (2011)

Latitude: 42°49'28.48" N. Longitude: 123°44'28.84" W.