

PRIMARY CORNER DESCRIPTION E. 1/4 Cor. for Sec. 1 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Resurvey by Fred Mensch and Gerald A. Sorrels, Surveyors under Special Instructions, Group #35, dated Dec. 22, 1916 - (DCSO records Vol. 21 Page(s) 8849)

Set an iron post 5 ft. long, 1" dia., 26" in the ground for 1/4 cor. of sec. 1 only, with brass cap mkd. 1/4 S1
1917

from which
A Cedar 24" dia., bears S.77°W., 34 lks. dist. mkd. 1/4 S1 BT
A Hemlock 12" dia., bears N.70°W., 39 lks. dist. mkd. 1/4 S1 BT.

Douglas Co. Surveyors Office - John M. Powell, and crew - July 1967 - C.S. File 54/44-68

Found - 1917 GLO brass cap, properly marked.
24" now 25" Cedar snag, S.77°W., 22.4 ft., shows good scribe.
No trace of NW. BT.
New BTs- 42" D.Fir S.64°W., 23.5 ft. mkd. 1/4 S1 CS BT.
36" D.Fir N.82 1/2°W., 47.5 ft. mkd. 1/4 S1 CS BT.
Corner lies 100 ft. West of creek.

David Edwards - Crew: Brant Miller & Eric Sprinkle - 1/4/2018 - C.S. File 65/102-9

Found - 1917 GLO brass capped iron pipe with the top 12" of same broken off and lying on the ground.
A 50" dia. Fir with healed blaze bears S.64°W., 23.5' (1967 BT)
A 38" dia. Fir snag with healed blaze bears N.82 1/2°W., 47.5' (1967 BT)
Original Cedar BT is a windfall.
Set - Remove broken iron pipe and set a 5/8"x30" steel rebar with a 2 1/2" dia. aluminum cap mkd "T32S R9W 1/4 S1" and "LS 2339" and "Roseburg Resources Co."
New - A 12" dia. Cedar scribed "1/4 S1 BT" bears N.43°W., 22.0'
A six foot steel post is set 2 feet North.
Note - Declination 15° East.