

TOWNSHIP 33 RANGE 04 POINT IDENTIFIER # 200700

PRIMARY CORNER DESCRIPTION C C for Secs. 5 & 6 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Edward F. Sharp, Deputy Surveyor, under Contract #617, dated June 3, 1893 (DCSO records Vol. 21 Page(s) 8946)

At point for closing cor. to secs. 5 and 6, I set a basaltic stone, 12 x 7 x 7 ins., 8" in the ground, marked with 5 notches on E. and 1 notch on W. edges, from which
A Fir 10" dia., bears S.25°E., 40 lks. dist., marked T33S R4W S5 BT.
A Fir 8" dia., bears S.72°W., 33 lks. dist., marked T33S R4W S6 BT.
A Fir 6" dia., bears N.62°E., 71 lks. dist., marked T33S R4W C C S5 and 6 BT.

BLM resurvey by Lynn M. Roseberry and Rollin D. Aanrud, Cadastral Surveyors, Under Group #865, surveyed July/Oct. 1975 (DCSO records Vol. 42 Page(s) 16537)

Point for the closing cor. of secs. 5 and 6, T33S R4W, at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 28 ins. long, 2 1/2 ins. dia., 24 ins. in the ground, with brass cap marked
T 32 S
S 32
S 6 | S 5
C C
T 33 S R 4 W
1975
from which
A Cedar 10" dia., bears S.2¼°E., 116 lks. dist., mkd. T33S R4W S5 CC BT.
A Fir 7" dia., bears S.36°W., 134½ lks. dist., mkd. T33S R4W S6 CC BT.

Fd. Brass cap, BLM Millsite survey by Larry J. Friar, July/Nov. 1983, (DCSO records, Vol. 45 Pages 17239-40)

Fd. Ok by Ken Hoffine, 3/2005 - M147-57 A&B