

TOWNSHIP 33 RANGE 05 POINT IDENTIFIER # 200640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 5 and 6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Edward F. Sharp, Deputy Surveyor, under Contract #617, dated June 3, 1893 (DCSO records Vol. 21 Page(s) 8997)

Set a basaltic stone 18 x 8 x 6 ins., 12" in the ground for 1/4 sec. cor. marked 1/4 on W. side, from which
A Fir 18" dia., bears N.17°E., 90 lks. dist., mkd. 1/4 S BT
A Fir 40" dia., bears S.19°W., 55 lks. dist., mkd. 1/4 S BT

Douglas Co. Surveyors Office - John M. Powell, Frank Jones, Joe Brady, crew - August, 1967 - C.S. File 53/52-15

Found - Orig. 40" D.Fir now 48" stump, S.19°W., 36.3 ft., stump had been opened, scribe visible "1/4S".
Orig. 18" D.Fir, now rotten stump N.17°E., 59.4 ft.
No trace of corner stone.

Set Brass cap at cor. mkd: County Surveyors Office
T 33 S R 5 W
1/4 S 6 | S 5
1967

New BTs -12" D.Fir S.19°W., 2.8 ft. mkd. 1/4 S6 CS BT.
13" D.Fir S.44 1/2°E., 15.6 ft. mkd. 1/4 S5 CS BT.

Fd. & used on BLM dependent resurvey by Terrence O. Nickerson, Cadastral Surveyor under Group #1474 survey Feb. 1989/June 1992 - (DCSO records Vol. 53 Pg(s) 20360-1)

Fd. Ok by K DeGroot, 11/2006 - C.S. File 65/59-5