

TOWNSHIP 33 RANGE 06 POINT IDENTIFIER # 300540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 8 and 9

|             |                   |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

GLO survey by W.H. Byars, Deputy Surveyor under contract # 431 survey dated March 29 1882 (DCSO records Vol. 21 Page(s) 9016)

-----

Set Chinquapin post, 40" long, 4" sq., 20" in the ground, marked ¼ S on W. face, for the ¼ sec. cor., from which  
A Cedar 12" dia., bears S.43°E., 36 lks. dist. marked ¼ S BT.  
A Fir 16" dia., bears N.32°W., 45 lks. dist. marked ¼ S BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones, Joe Brady, crew - Oct. 1967 - C.S. File 54/53-38

-----

Found - Orig. 12" now 22" Cedar S.43°E., 23.8 ft., shows good scribing of "¼S BT" in the wood.  
Orig. 16" Fir now windfall, N.32°W., 29.7 ft., no trace of scribing.

Set Brass cap at cor. mkd: County Surveyors Office  
T 33 S R 6 W  
¼ S 8 | S 9  
1967

Rescribed -  
22" Cedar S.43°E., 23.8 ft. scribed "¼ S9 CS BT"  
New BT - 5" Alder N.34°E., 7.0 ft. scribed "S8 CS BT".  
No other BT in range for scribing.  
This corner lies 130.0 ft. South of creek and corner lies in old cutting unit.

Fd. OK, by G. Nygren, March 1994, M 118-79

Fd. & used on BLM dependent resurvey by Francis J. Simon, Cadastral Surveyor under Group #1736, surveyed June/Sept. 1994 - (DCSO records Vol. 52 Page(s) 19731-2)