

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 2 and 11

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Wells Lake and Geo. W. Hyde, Deputy Surveyors, under Contract #54, dated Feb. 19, 1855 (DCSO records Vol. 21 Page(s) 9005)

Set qr. sec. post, from which
 A Laurel 3" dia., bears S.11°W., 18 lks.
 A B.Oak 15" dia., bears N.54°E., 49 lks.

Survey by H.W. Lawrence - March 24, 1955 - C.S. File 41/355

Corner set by proportionate measurement.
 Set a 1/2" iron rod 36" long, driven 30" into ground, from which
 A B.Oak 10" dia., bears N.34°20'W., 69 ft. mkd. 1/4 S2 BT 1543.
 A B.Oak 17" dia., bears S.21°13'E., 40 ft. mkd. 1/4 S11 BT 1543.

George J. Wenderoth - August 1955 - C.S. File 47/7

I drive a 3/4" pipe over 3/8" iron rod.

Fd. OK, by J. Hollingsworth, July 5, 1988, C.S. File 63/62 and M 107-16

BLM dependent resurvey by Francis J. Simon, Cadastral Surveyor under Group #1736, surveyed June/Sept. 1994 - (DCSO records Vol. 52 Page(s) 19724-5)

The 1/4 sec. cor. of secs. 2 & 11, reestablished at proportionate measurement by Lawrence, in 1955, recorded in survey No. 33-55, utilized by Thompson, in 1962, and subsequently utilized by Hollingsworth, in 1988. There is no remaining evidence of the original corner, therefore this position is accepted as the corner; monumented with an iron pipe, 3/4 in. diam., firmly set, projecting 13 ins. above the ground, from which bearing trees mkd. by Lawrence:

- A B.Oak, 21" diam. bears S.21 1/4°E., 62 lks. w/healed double blaze
- A B.Oak, 14" dia. bears N.34 1/4°W., 104 1/2 lks w/healed double blaze

At the corner point

Set a stainless steel post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, directly over the iron pipe, with brass cap mkd.

T33S R6W
 1/4 S 2
 S 11
 1994

Deposit a white "DEEP-1" magnetic marker at base of stainless steel post.

Cont.

TOWNSHIP 33 RANGE 06 POINT IDENTIFIER # 540600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 2 and 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM dependent resurvey by Kevin G Mulder, Cadastral Surveyor, under Group No. 2925; Surveyed July/Oct. 2018 - (DCSO records Vol. 59 Page(s) 23780)

The ¼ sec. cor. of secs. 2 and 11, reported by Simon in 1994, monumented with a stainless steel post, 2½" dia., firmly set, projecting 2" above the ground, with brass cap (properly) mkd from which a bearing tree reported by Simon

A black oak, 22" dia., bears S.21¼°E., 40.9 ft., with a healed double blaze.

and a new bearing tree

A madrone, 7" dia., bears N.59½°W., 19.8 ft., mkd. ¼ S2 BT

NAD 1983 (2011)

Latitude: 42°43'29.77" N. Longitude: 123°22'35.97" W.